LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

AIG Building, 78 Shenton Way #09-16

Singapore 079120

Paya Ubi Industrial Park Singapore 408933

Date: 04 Aug 2020 Attn: Nadaraja, Deeban

Preliminary Advice

Vehicle No : SGU9368L Accident Date : 25/07/2020 Make : AUDI A4 Policy No. : 2100478816-03 : 27/07/2020 Excess Assignment Date : S\$300.00 Est. Duration of Repair Date of Inspection : 28/07/2020 : 15

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	112,240.00
Revised Amount	:S\$	64,035.00
Check Items (Estimated)	:S\$	21,188.00
Total	:S\$	85,223.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	55,292.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,708.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(X	()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :