

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautop@gmail.com

SJE : _____ Vehicle Nos : **SMC 8312 C**
Date of Survey : _____ Model : Mercedes C180
Date of ReSurvey: _____ After-Paint: _____ Year : _____
Contacts : _____ Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit \$	TOTAL \$	
1	Front bumper	1	\$ 1,698.60	\$ 1,698.60	BR✓
2	Front bumper inner sponge	1	\$ 234.80	\$ 234.80	BR✓
3	Front bumper side retainer	2	\$ 53.90 98.60	\$ 106.00	NG✓
4	Front bumper fog lamp garnish LH	1	\$ 72.68	\$ 72.68	NG✓
5	Front bumper outer chrome garnish	1	\$ 385.60	\$ 385.60	NDX✓
6	Front bumper sensor	1	\$ 310.45	\$ 310.45	DL✓
7	Front support panel	1	\$ 952.89	\$ 952.89	NDX✓
8	Front support panel top garnish	1	\$ 345.20	\$ 345.20	
9	Front fender LH	1	\$ 988.46	\$ 988.46	RX
10	Front fender inner cowling LH	1	\$ 415.30	\$ 415.30	BR✓
11	Headlamp LH	1	\$ 2,610.20	\$ 2,610.20	BR✓
12	Headlamp lower bracket LH	1	\$ 375.60	\$ 375.60	
13	Front shock absorber LH	1	\$ 634.70	\$ 634.70	
14	Front lower arm LH	1	\$ 486.40	\$ 486.40	NDX✓
15	Front knuckle arm LH	1	\$ 785.30	\$ 785.30	
16	Front knuckle arm bearing LH	1	\$ 285.60	\$ 285.60	JMY✓
			Parts Sub Total :	\$ 5112.48	11,089.43
			10% Discount :	\$ 511.25	3,108.94
			PARTS TOTAL :	\$ 5,980.49	

Nos.	SPECIAL NETT	Qty	Unit \$	TOTAL \$	
1	Sundries	1	\$ 80.00	\$ 80.00	NDX✓
2	Front bumper clips	1	\$ 60.00	\$ 60.00	NEG✓
3	Front grille clips	1	\$ 60.00	\$ 60.00	
4	Front support panel sealant	1	\$ 100.00	\$ 100.00	NDX✓
5	Front support panel top garnish clips	1	\$ 60.00	\$ 60.00	
6	Front fender sealant	1	\$ 100.00	\$ 100.00	
7	Front fender inner cowling clips	1	\$ 60.00	\$ 60.00	NEG✓
8	Front alloy rim LH	1	\$ 880.00	\$ 880.00	NDX✓
9	Front tyre LH	1	\$ 480.00	\$ 480.00	
			SPECIAL NETT TOTAL :	\$ 1,880.00	

SMC 8212C

Not.	LABOUR		SS
1	R&R front bumper sensor	\$ 60.00	-60.00
2	R&R front under carriage	\$ 80.00	150.00
3	R&R front tyre and balancing	\$ 30.00	60.00
4	Wheel alignment	\$ 60.00	-120.00
5	Diagnostic reset fault code	\$ 80.00	300.00
6	Check wiring	\$ 50.00	150.00
7	Upholstery	\$	-300.00
8	Panel beat	\$ 600.00	1,000.00
9	Rust proofing	\$	-200.00
10	Spray painting	\$ 480.00	1,000.00
LABOUR TOTAL:		\$	3,380.00

Survey 28/7/2020
TTCIM Win
1400 hrs

Resurvey 29/7/2020
TTCIM
1300 hrs

PARTS TOTAL: \$ 9,980.49
SPECIAL NETT TOTAL: \$ 1,880.00
LABOUR TOTAL: \$ 3,380.00
GRAND TOTAL: \$ 15,240.49

Unup sum repair
Repair days 5

PARTS 4,601.23
S/N 260.00
L2BWR 1,360.00
6,221.23
@ 20% 1,244.24
4,976.99

L/S 4950/2

TTCIM
17/8/2020

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer:
Signature:
Date: