

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Jul 2020)
 Parts: N/A NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/GBF1716G/27/07/2020 15:46
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*ROOF LINING / CR4	0.00	0.00	*980.00 F
2	1		*FRONT WINDSCREEN GLASS / BR	0.00	0.00	*680.00 F
3	1		*FRONT WINDSCREEN PILLAR LH / DD	0.00	0.00	*850.00 F
4	1		*FRONT WIPER GARNISH / CUT	0.00	0.00	*120.00 F
5	1		*FRONT WIPER CORNER GARNISH LH / CUT	0.00	0.00	*28.00 F
6	1		*FRONT WIPER BLADE RH / CUT	0.00	0.00	*30.00 F
7	1		*FRONT WIPER BLADE LH / CUT	0.00	0.00	*30.00 F
8	1		*FRONT WINDSCREEN PILLAR INNER GARNISH LH / CR4	0.00	0.00	*95.00 F
9	1		*FRONT SIDE PANEL LH / DD	0.00	0.00	*225.00 F
10	1		*FRONT PANEL / DD	0.00	0.00	*600.00 F
11	1		*FRONT HEADLAMP RH X NN	0.00	0.00	*225.00 F
12	1		*FRONT HEADLAMP LH / BR	0.00	0.00	*228.00 F
13	1		*FRONT HEADLAMP PANEL LH / DD	0.00	0.00	*210.00 F
14	1		*FRONT GRILLE / BR	0.00	0.00	*280.00 F
15	1		*FRONT GRILLE EMBLEM / MC	0.00	0.00	*50.00 F
16	8		*FRONT GRILLE CLIP / MC	0.00	0.00	*40.00 F
17	1		*FRONT BUMPER / BR	0.00	0.00	*280.00 F
18	1		*FRONT BUMPER SIDE BRACKET LH / MIS	0.00	0.00	*80.00 F
19	1		*FRONT BUMPER REINFORCEMENT / DD	0.00	0.00	*400.00 F
20	1		*FRONT BUMPER FOAM X NN	0.00	0.00	*135.00 F
21	1		*FRONT BUMPER FOGLAMP LH / MIS	0.00	0.00	*225.00 F
22	1		*FRONT BUMPER FOGLAMP COVER LH / MIS	0.00	0.00	*75.00 F
23	1		*FRONT BUMPER VERTICAL BRACKET LH / MIS	0.00	0.00	*65.00 F
24	1		*FRONT BUMPER LOWER GRILLE X NN	0.00	0.00	*110.00 F
25	1		*FRONT BUMPER TOW COVER X NN	0.00	0.00	*20.00 F
26	10		*FRONT BUMPER CLIP / MC	0.00	0.00	*20.00 F
27	1		*AIR DUCT TOP X NN	0.00	0.00	*100.00 F
28	1		*AIR DUCT LOWER X NN	0.00	0.00	*160.00 F
29	1		*FRONT DOOR LH / DD	0.00	0.00	*720.00 F
30	1		*FRONT DOOR HINGE TOP LH / BT	0.00	0.00	*55.00 F
31	1		*FRONT DOOR HINGE LOWER LH / BT	0.00	0.00	*55.00 F
32	1		*FRONT DOOR CHECKER LH X NN	0.00	0.00	*40.00 F
33	1		*FRONT DOOR RUBBER LH / TA	0.00	0.00	*80.00 F
34	1		*FRONT DOOR LOCK INNER LH / BT	0.00	0.00	*135.00 F
35	1		*FRONT DOOR GLASS LH / BR	0.00	0.00	*380.00 F
36	1		*FRONT DOOR OUTER MOULDING LH / BT	0.00	0.00	*95.00 F
37	1		*FRONT DOOR REGULATOR LH / BT	0.00	0.00	*110.00 F
38	1		*FRONT DOOR REGULATOR MOTOR LH X NN	0.00	0.00	*270.00 F
39	1		*FRONT DOOR TRIMBOARD LH / CR4	0.00	0.00	*350.00 F
40	1		*FRONT DOOR HANDLE COVER INNER LH / CR4	0.00	0.00	*45.00 F
41	1		*FRONT DOOR SPEAKER LH X NN	0.00	0.00	-
			CHECK PRICE			
42	1		*FRONT DOOR FAME RUBBER LH / TN	0.00	0.00	*90.00 F
43	1		*DASHBOARD X NN	0.00	0.00	*700.00 F
44	1		*DASHBOARD REINFORCEMENT X NN	0.00	0.00	*380.00 F

Kan Fook Sing Motor Workshop/GBF1716G/27/07/2020 15:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*AIR CON BLOWER <i>1</i> ✓ BR	0.00	0.00	*550.00 F
46	1		*HEATER UNIT <i>1</i> ✓ BR	0.00	0.00	*1,600.00 F
47	1		*FRONT STEP GARNISH LH <i>BR</i>	0.00	0.00	*65.00 F
48	1		*FRONT STEP PANEL LH <i>DO</i>	0.00	0.00	*55.00 F
49	1		*FRONT WHEEL ARCH GARNISH LH <i>BR</i>	0.00	0.00	*125.00 F
50	1		*CENTRE PILLAR LH <i>X R</i>	0.00	0.00	*800.00 F
51	1		*FRONT WHEEL RIM LH <i>DT</i>	0.00	0.00	*250.00 F
52	1		*FRONT HUP CAP LH <i>BR</i>	0.00	0.00	*130.00 F
53	1		*FRONT SHOCK ABSORBER LH <i>1</i> X NN	0.00	0.00	*130.00 F
54	1		*FRONT LOWER ARM LH <i>1</i> X NN	0.00	0.00	*160.00 F
55	1		*FRONT KNUCKLE ARM LH <i>1</i> X NN	0.00	0.00	*280.00 F
56	1		*FRONT KNUCKEL BEARING LH <i>1</i> X NN	0.00	0.00	*120.00 F
57	1		*FRONT STABILZIER LINK LH <i>1</i> X NN	0.00	0.00	*75.00 F
58	1		*STEERING TIE ROD LH <i>1</i> X NN	0.00	0.00	*85.00 F
59	1		*STEERING TIE ROD END LH <i>1</i> X NN	0.00	0.00	*80.00 F

F=Franchise part.

Sub Total (\$\$) 14,351.00 *12,461*
+ Margin on L,N Items 15.00% (\$\$) 2,152.65
Total Parts (\$\$) 16,503.65

Kan Fook Sing Motor Workshop/GBF1716G/27/07/2020 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COMPANY ADV / <i>MC</i>	15.00
2	1	ERP STICKER / <i>MC</i>	10.00
3	1	FRONT NUMBER PLATE X NN	30.00
4	1	FRONT WINDSCREEN GUM / <i>MC</i>	40.00
Sub Total (S\$)			95.00 <i>65</i>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	1,600.00 <i>1200</i>
<u>Labour Items</u>			
2	TO CHECK WIRIGN SYSTEM	New	30.00 /
3	TO CHECK ALIGNMENT	New	80.00 /
4	TO REMOVE/REFIT DASHBOARD	New	240.00 <i>150</i>
5	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00 /
6	TO REMOVE/REFIT FRONT UNDERCARRIAGE LH	New	180.00 /
7	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	40.00 /
8	TO REMOVE/REFIT AND REPALCE ROOF LINING	New	120.00 <i>80</i>
9	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	New	180.00 <i>120</i>
10	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	2,380.00 <i>1800</i>
Gross Labour Cost (S\$)			4,950.00 <i>3780</i>

Kan Fook Sing Motor Workshop/GBF1716G/27/07/2020 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

00 - Not Authorize

EX (PS) - \$2200

28/7/20, 12.00pm

L/S

My AL My

14 days

Parts \$12,461.00

SGS \$ 1,010.00

\$ 13,471.00

Nett \$ 65.00

2hr \$ 3780.00

\$ 17,316.00

20% \$ 3,463.20

\$ 13,852.80

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 18 Sep 2020)**Parts:** N/A NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Kan Fook Sing Motor Workshop/GBF1716G/18/09/2020 16:54**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*OIL COOLER DD	0.00	0.00	*480.00 F
2	1		*AUTO COOLER PIPE BT	0.00	0.00	*130.00 F
3	1		*ENGINE CONTROLLER UNIT BR	0.00	0.00	*400.00 F
Sub Total (S\$)						1,010.00
+ Margin on L,N Items 15.00% (S\$)						151.50
Total Parts (S\$)						1,161.50

F=Franchise part.

Kan Fook Sing Motor Workshop/GBF1716G/18/09/2020 16:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS