

HC AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co and GST Reg. No.: 200820153N

Date : 28 / 07 / 2020

ESTIMATE COSTS OF REPAIR

M/s SJ Motor Enterprise
C/o 160 Sin Ming Drive
05-09 Sin Ming Auto City
Singapore 575722

Not Notchail
6/1/2020 & 9550k
Resuming After Paint
7days

Dear Sir / Madam,

Vehicle no. : SLP 2169 H - Toyota Camry 2.0 (A)
Accident date : 27 / 07 / 2020

Quantity	Descriptions	Amount (S\$)
1	1 pc bonnet	\$ 1,028.75
2	1 pc n/s bonnet hinge	\$ 52.60
3	1 pc front grille	\$ 549.80
4	1 pc n/s head lamp	\$ 1,810.80
5	1 pc n/s head lamp lower bracket	\$ 98.35
6	1 pc front bumper fascia	\$ 1,923.10
7	1 pc front bumper sponge	\$ 102.00
8	1 pc front bumper reinforcement	\$ 511.30
9	1 pc n/s front bumper side retainer	\$ 60.30
10	1 pc n/s front bumper chrome moulding (near fog lamp)	\$ 150.03
11	1 pc n/s fog lamp	\$ 292.30
12	1 pc n/s front fog lamp cover	\$ 150.50
13	5 pcs front bumper clip 1 @ 3.50	\$ 17.50
14	1 pc n/s front fender	\$ 800.50
15	1 pc n/s front fender 'VVT-i' emblem	\$ 83.60
16	1 pc n/s front fender inner garnish	\$ 153.20
17	11 pcs n/s front fender inner garnish clips 1 @ 3.00	\$ 33.00
18	1 pc n/s front fender top garnish	\$ 202.70
19	1 pc n/s front fender inner sponge	\$ 187.70
20	1 pc front support panel	\$ 959.70
21	1 pc n/s front door	\$ 1,087.09
22	2 pcs n/s front door hinge 1 @ 75.61	\$ 151.22
23	1 pc n/s front rocker panel	\$ 480.12
24	1 pc n/s front rocker panel garnish	\$ 617.87
25	1 pc n/s front shocker absorber	\$ 425.90
26	1 pc n/s front lower arm	\$ 602.00
27	1 pc n/s front knuckle arm	\$ 583.60
28	1 pc n/s front knuckle arm bearing	\$ 171.70
	Balance C/FD	\$ 13,287.23

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co and GST Reg. No. : 200820153N

Balance B/FD (SLP 2169 H)

\$ 13,287.23

29 1 pc n/s front anti roll bar side link
30 1 pc n/s front drive shaft *1834-20*

SP13 \$ 181.36
AR \$ 1,930.20
\$ 15,398.79
\$ 3,849.70
\$ 11,549.09

Less 25 %

31 1 pc n/s front wheel tyre
32 1 pc n/s front wheel rim

PR \$ 385.00 *sn 202in*
AR \$ 1,200.00 *sn 382in*
\$ 13,134.09

Labour charges

\$ 1,800.00 *700l*

To putty and spray painting

\$ 1,600.00 *1200l*

Re-seal anti rust

\$ 200.00 *90l*

Towing fee

\$ 120.00 *50l*

To check, replace, repair wiring

\$ 120.00 *30l*

To check wheel alignment

\$ 120.00 *60l*

Remove and refix n/s front undercarriage

\$ 450.00 *180l*

Plus 7 % GST

\$ 17,544.09

Grand total

\$ 1,228.09

\$ 18,772.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: