

ASS. REG. BY:

REF:

Smo/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OO/15/NS/LP/RES/100/RES/15/VA/INV/INV

To Insured Vehicle No:

at Workshop ins

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

7/22

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLP 21694

Yr Regn:

09, 07

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Camry

C.G.

1998

Colour

MR. WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

328431

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 0538K410 7015733

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Privanti

Front

Rear

R/Bal.

4

mm

R/Bal.

3

mm

L/Bal.

4

mm

L/Bal.

3

mm

D.O.A.

27/7/20

D.O.I.

28/7/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR &amp; 46

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA not ready

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

1/9/20-Typist

Report Format: TP

Lump Sum H.B.: (\$ 9650)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fees:

Others

TOTAL

# H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co and GST Reg. No. : 200820153N

Date : 28 / 07 / 2020

## ESTIMATE COSTS OF REPAIR

M/s SJ Motor Enterprise

C/o 160 Sin Ming Drive

# 05-09 Sin Ming Auto City

Singapore 575722

*Not withold  
6/1/2020 &  
Reserve After Paint  
7 days*

Dear Sir / Madam ,

Vehicle no. : SLP 2169 H - Toyota Camry 2.0 (A)

Accident date : 27 / 07 / 2020

| Quantity | Descriptions                                          | Amount ( S\$ )          |
|----------|-------------------------------------------------------|-------------------------|
| 1        | 1 pc bonnet                                           | \$ <i>BN</i> 1,028.75 ✓ |
| 2        | 1 pc n/s bonnet hinge                                 | \$ <i>BN</i> 52.60 ✓    |
| 3        | 1 pc front grille                                     | \$ <i>CM</i> 549.80 ✓   |
| 4        | 1 pc n/s head lamp                                    | \$ <i>BN</i> 1,810.80 ✓ |
| 5        | 1 pc n/s head lamp lower bracket                      | \$ <i>BN</i> 98.35 ✓    |
| 6        | 1 pc front bumper fascia                              | \$ <i>CM</i> 1,923.10 ✓ |
| 7        | 1 pc front bumper sponge                              | \$ <i>BN</i> 102.00 X   |
| 8        | 1 pc front bumper reinforcement                       | \$ <i>R</i> 511.30 X    |
| 9        | 1 pc n/s front bumper side retainer                   | \$ <i>CM</i> 60.30 ✓    |
| 10       | 1 pc n/s front bumper chrome moulding (near fog lamp) | \$ <i>BN</i> 150.03 ✓   |
| 11       | 1 pc n/s fog lamp                                     | \$ 292.30 ?             |
| 12       | 1 pc n/s front fog lamp cover                         | \$ <i>BN</i> 150.50 X   |
| 13       | 5 pcs front bumper clip 1 @ 3.50                      | \$ <i>BN</i> 17.50 ✓    |
| 14       | 1 pc n/s front fender                                 | \$ <i>BN</i> 800.50 ✓   |
| 15       | 1 pc n/s front fender 'VVT-i' emblem                  | \$ <i>BN</i> 83.60 ✓    |
| 16       | 1 pc n/s front fender inner garnish                   | \$ <i>CM</i> 153.20 ✓   |
| 17       | 11 pcs n/s front fender inner garnish clips 1 @ 3.00  | \$ <i>BN</i> 33.00 ✓    |
| 18       | 1 pc n/s front fender top garnish                     | \$ <i>BN</i> 202.70 ✓   |
| 19       | 1 pc n/s front fender inner sponge                    | \$ 187.70 ?             |
| 20       | 1 pc front support panel                              | \$ <i>BN</i> 959.70 ✓   |
| 21       | 1 pc n/s front door                                   | \$ 1,087.09 ?           |
| 22       | 2 pcs n/s front door hinge 1 @ 75.61                  | \$ <i>R</i> 151.22 X    |
| 23       | 1 pc n/s front rocker panel                           | \$ <i>R</i> 480.12 X    |
| 24       | 1 pc n/s front rocker panel garnish                   | \$ <i>BN</i> 617.87 ✓   |
| 25       | 1 pc n/s front shocker absorber                       | \$ 425.90 ?             |
| 26       | 1 pc n/s front lower arm                              | \$ 602.00 ?             |
| 27       | 1 pc n/s front knuckle arm                            | \$ <i>BN</i> 583.60 ✓   |
| 28       | 1 pc n/s front knuckle arm bearing                    | \$ <i>BN</i> 171.70 ✓   |
|          | Balance C/FD                                          | \$ 13,287.23            |

# H C AUTO PTE LTD

160 Sin Ming Drive # 03-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co and GST Reg. No. : 200820153N

Balance B/FD (SLP 216911)

\$ 13,287.23

29 1 pc n/s front anti roll bar side link

\$ 181.36 7

30 1 pc n/s front drive shaft

\$ 1,930.20 7

\$ 15,398.79

Less 25 %

\$ 3,849.70

\$ 11,549.09

31 1 pc n/s front wheel tyre

Pr \$ 385.00 sn 2061m

32 1 pc n/s front wheel rim

Pr \$ 1,200.00 sn 3881m

\$ 13,134.09

Labour charges

\$ 1,800.00 7001

To putty and spray painting

\$ 1,600.00 12001

Re-seal anti rust

\$ 200.00 901

Towing fee

\$ 120.00 501

To check, replace, repair wiring

\$ 120.00 301

To check wheel alignment

\$ 120.00 601

Remove and refix n/s front undercarriage

\$ 450.00 1801

\$ 17,544.09

Plus 7 % GST

\$ 1,228.09

Grand total

\$ 18,772.18

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Enquire PARF/COE Rebate for Registered Vehicle

| Owner Details                                                                                                                                                                                                           |                           |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|
| Owner ID Type:                                                                                                                                                                                                          | Business                  |
| Owner ID:                                                                                                                                                                                                               | 801X                      |
| Vehicle Details                                                                                                                                                                                                         |                           |
| Vehicle No.:                                                                                                                                                                                                            | SLP2169H                  |
| Vehicle to be Exported:                                                                                                                                                                                                 | Yes                       |
| Intended Deregistration Date:                                                                                                                                                                                           | 27 Jul 2020               |
| Vehicle Make:                                                                                                                                                                                                           | TOYOTA                    |
| Vehicle Model:                                                                                                                                                                                                          | CAMRY 2.0 AUTO ABS AIRBAG |
| Primary Colour:                                                                                                                                                                                                         | White                     |
| Manufacturing Year:                                                                                                                                                                                                     | 2007                      |
| Engine No.:                                                                                                                                                                                                             | 1AZE055347                |
| Chassis No.:                                                                                                                                                                                                            | MR053BK4107015733         |
| Maximum Power Output:                                                                                                                                                                                                   | 108.0 kW (144 bhp)        |
| Open Market Value:                                                                                                                                                                                                      | \$26,761.00               |
| Original Registration Date:                                                                                                                                                                                             | 19 Sep 2007               |
| First Registration Date:                                                                                                                                                                                                | 19 Sep 2007               |
| Transfer Count:                                                                                                                                                                                                         | 3                         |
| Actual ARF Paid:                                                                                                                                                                                                        | \$29,438.00               |
| Intended PARF Rebate Details                                                                                                                                                                                            |                           |
| PARF Eligibility:                                                                                                                                                                                                       | Forfeited                 |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | -                         |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$0.00                    |
| Intended COE Rebate Details                                                                                                                                                                                             |                           |
| COE Expiry Date:                                                                                                                                                                                                        | 31 Jul 2022               |
| COE Category:                                                                                                                                                                                                           | B - Car (1601cc & above)  |
| COE Period(Years):                                                                                                                                                                                                      | 5                         |
| PQP Paid:                                                                                                                                                                                                               | \$26,237.00               |
| COE Rebate Amount:                                                                                                                                                                                                      | \$10,551.00               |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$10,551.00</b>        |
| Message                                                                                                                                                                                                                 |                           |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                           |

The information contained herein is correct as at 27 Jul 2020

OK