

ASS. REC. BY: TGTUM

REF:

CC4/AIC20007761/BK03

ASSIGNMENT

From: _____ Date: 28/7/2020

Veh No: SDY 6269Z Yr Regn: 17/3/2008

Estimated Cost: _____

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SDY 6269Z

Make: Nissan Sunny C.C. 1597

at Workshop m/s Dean Autopro

Colour: Beige A/C: Insured / Std / NI / NA

of 160 Singing Dr, # 01-14

Sp. Reading: 324151 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: QG16426179

Policy No. _____

C/No: JNICFAN16Z0109865

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: Inorder / Jammed / Leaked / Burnt or _____

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or _____

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 195/65/15

R: 195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Bal. or Market Value: 32,000/- with body

Front Rear

IDAC Accident Rport: _____ Consistent?: Yes or No

R/Bal. 6 mm R/Bal. 6 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: _____ days Res.: Yes or No

D.O.A. _____ D.O.I. 28/7/2020

Lump Sum: _____ % 3 Val.: Yes or No

Survey held at Dean Autopro

CA / REV / REP. / 24 HRS WP

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	L/S 5950/-
	Cor recommended is NV 2050/-, Hs being higher than NV TGTUM Min. 3/8/2020
	MV 32,000/- with body PV 29,920/- NV 2080/- TGTUM Min. 3/8/2020

Date/Time, File Pass to? : Preli. Report

Days Of Repair: _____

1) : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2) _____

Transportation: _____

Add Fee: : Site Insp (\$ _____)

\$ + RS. _____ SI

: Interview (\$ _____)

Photos _____

: Tech. Invs (\$ _____)

Others _____

: Weekend (\$ _____)

TOTAL _____

Rep. Format: _____

Lump Sum / L.S. (\$) _____

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SDY 6269 Z**
 Model : Nissan Sunny
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 782.60	\$ 782.60	DDV
2	Bootlid logo	1	\$ 108.90	\$ 108.90	
3	Bootlid emblem 'Sunny'	1	\$ 118.60	\$ 118.60	
4	Bootlid emblem 'EX Saloon'	1	\$ 103.60	\$ 103.60	NEC
5	Bootlid emblem 'CVTC'	1	\$ 97.00	\$ 97.00	
6	Bootlid emblem 'E- Throttle'	1	\$ 69.00	\$ 69.00	
7	Bootlid outer chrome garnish	2	\$ 486.20	\$ 972.40	BRV
8	Bootlid inner trim board	1	\$ 198.30	\$ 198.30	NDX
9	Bootlid number plate lamp	2	\$ 86.40	\$ 172.80	NDX
10	Bootlid weatherstrip	1	\$ 286.30	\$ 286.30	DE✓
11	Bootlid hinge	1	\$ 186.90	\$ 186.90	BT✓
12	Bootlid lock	1	\$ 214.50	\$ 214.50	JMV
13	Bootlid striker	1	\$ 96.40	\$ 96.40	NDX
14	Rear bumper	1	\$ 595.20	\$ 595.20	DDV
15	Rear bumper outer chrome moulding	1	\$ 184.60	\$ 184.60	DDV
16	Rear bumper side retainer	2	\$ 87.40	\$ 174.80	NEC
17	Rear bumper reinforcement stopper	2	\$ 168.00	\$ 336.00	NDX
18	Rear end panel	1	\$ 583.60	\$ 583.60	DDV
19	Rear end panel top garnish	1	\$ 196.50	\$ 196.50	BRV
20	Rear fender	1	\$ 788.60	\$ 788.60	RT
21	Rear fender inner trim board	2	\$ 214.90	\$ 429.80	NDX
22	Rear fender air vent	1	\$ 181.50	\$ 181.50	NDX
23	Rear windscreen moulding	1	\$ 184.20	\$ 184.20	NNX
24	Spare tyre panel	1	\$ 898.60	\$ 898.60	DDV
25	Spare tyre top borad	1	\$ 241.80	\$ 241.80	NDX
26	Taillamp	2	\$ 432.40	\$ 864.80	BRV
27	Taillamp lower braket	2	\$ 65.40	\$ 130.80	NSX
28	Taillamp base panel	2	\$ 214.80	\$ 429.60	RT
29	Exhaust pipe	1	\$ 855.00	\$ 855.00	
30	Exhaust mounting	1	\$ 79.50	\$ 79.50	NDX
Parts Sub Total :				\$ 4798.40	11,537.70
10% Discount :				\$ 479.84	1,153.77
PARTS TOTAL :				\$ 4318.56	10,383.93

SDY 6269Z

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ -80.00
2	Bootlid sealant	1	\$ 100.00	\$ 30.00 100.00
3	Bootlid outer chrome garnish clips	2	\$ 50.00	\$ 30.00 100.00
4	Rear end panel sealant	1	\$ 100.00	\$ 30.00 100.00
5	Rear bumper clips	1	\$ 50.00	\$ 30.00 -50.00
6	Rear end panel sealant	1	\$ 100.00	\$ -100.00
7	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 -50.00
8	Rear fender sealant	2	\$ 100.00	\$ 30.00 -200.00
9	Rear fender inner trim board clips	2	\$ 50.00	\$ -100.00
10	Rear windscreen seal	1	\$ 60.00	\$ 60.00
11	Rear windscreen sealant	1	\$ 100.00	\$ 100.00
12	Rear windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
13	Spare tyre panel sealant	1	\$ 100.00	\$ 30.00 -100.00
14	Taillamp clips	2	\$ 50.00	\$ -100.00
15	Taillamp seal	2	\$ 60.00	\$ -120.00
16	Taillamp base panel sealant	1	\$ 100.00	\$ 30.00 100.00
17	Rear number plate w/cowling	1	\$ 80.00	\$ 50.00 80.00
18	Reverse sensor with module	2	\$ 250.00	\$ 200.00 -500.00
19	Brakedown sign	1	\$ 120.00	\$ 120.00
SPECIAL NETT TOTAL :				\$ 730.00 2,240.00

NNX
NEC
RPT
NEC
NNX
NNX
NEC
NEC
NNX
NEC
BT
NNX

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 50.00 100.00
2	R&R reverse sensor and spray paint	\$ 60.00 100.00
3	R&R exhaust pipe	\$ 250.00
4	R&R fuel pipe	\$ 180.00
5	R&R rear windscreen	\$ 180.00
6	upholstery	\$ 300.00
7	Check wiring	\$ 30.00 80.00
8	Conduct water leakage test	\$ -60.00
9	Rust proofing	\$ 60.00 200.00
10	Spray painting	\$ 1200.00 1,800.00
11	Panel beat	\$ 1000.00 1,800.00
LABOUR TOTAL :		\$ 2400.00 5,050.00

NNX
NNX
NNX
NNX

Survey 28/7/2020
TGTIM Min
1430 hrs

Resurvey 29/7/2020
TGTIM Min
1315 hrs

ump sum repair
Repair days 9

PARTS TOTAL : \$ 4318.56 10,383.93
SPECIAL NETT TOTAL : \$ 730.00 2,240.00
LABOUR TOTAL : \$ 2400.00 5,050.00
GRAND TOTAL : \$ 17,673.93

7448.56
1489.71

5958.85

L/S 5950/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TGTIM
Min
3/8/2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9251
Vehicle Details	
Vehicle No.:	SDY6269Z
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Aug 2020
Vehicle Make:	NISSAN
Vehicle Model:	SUNNY 1.6EXA
Primary Colour:	Beige
Manufacturing Year:	2007
Engine No.:	QG16426179
Chassis No.:	JN1CFAN16Z0109805
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,045.00
Original Registration Date:	17 Mar 2008
First Registration Date:	17 Mar 2008
Transfer Count:	1
Actual ARF Paid:	\$12,045.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Mar 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$39,274.00
COE Rebate Amount:	\$29,920.00
Total Rebate Amount:	\$29,920.00

The information contained herein is correct as at 03 Aug 2020

OK

DOA 27/7/2020

COE left 7yrs 8mths

MV 32,000/2 (includes body)
PV 29,920/2
NV 2,080/2

hmr
31/8/2020