

Nett items					
S/N	Parts description		QTY	UNIT PRICE	AMOUNT
1	Front grille	479.30	mg/cm Sh	1	\$ 668.00 \$ 668.00
2	Front grille "NISSAN" logo		mc mm	1	\$ 56.00 \$ 56.00
3	Front bumper	571.90	Rvcl/cm	1	\$ 1,086.00 \$ 1,086.00
4	Front bumper bracket		R	2	\$ 146.00 \$ 292.00
5	Front bumper side retainer		ol/dy	2	\$ 109.00 \$ 218.00
6	Front bumper reinforcement		R	1	\$ 565.00 \$ 565.00
7	Front bumper reinforcement bracket		R	2	\$ 248.00 \$ 496.00
8	Front bumper foglamp o/s		mi/y	1	\$ 447.00 \$ 447.00
9	Front bumper foglamp garnish o/s	130.10	mi/y	1	\$ 198.00 \$ 198.00
10	Headlamp o/s	1182.	cm	1	\$ 1,294.00 \$ 1,294.00
11	Front door o/s		R	1	\$ 1,434.00 \$ 1,434.00
12	Front door hinge o/s		R	2	\$ 221.00 \$ 442.00
13	Front bumper lower grille		Sh	1	\$ 388.00 \$ 388.00
14	Quarter panel o/s		R	1	\$ 456.00 \$ 456.00
15	Turbo intercooler assy	2050.40	Pu	1	\$ 2,200.00 \$ 2,200.00
16	Turbo intercooler hose		Sh	2	\$ 89.00 \$ 178.00
17	Turbo intercooler side cowling		Sh	1	\$ 229.00 \$ 229.00
18	Turbo intercooler front cowling		Sh	1	\$ 337.00 \$ 337.00
19	Front door step garnish o/s	108	Ad/cm	1	\$ 221.00 \$ 221.00
20	Front door step panel o/s		R	1	\$ 342.00 \$ 342.00
Subtotal					\$ 11,547.00
List discount					10.00%
Total					\$ 10,392.30

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front grille clips	8	\$ 5.50	\$ 44.00
2	Quarter panel o/s clips	6	\$ 5.50	\$ 33.00
3	Front bumper clips	10	\$ 5.50	\$ 55.00
4	Front door step garnish o/s clips	6	\$ 5.50	\$ 33.00
5	Turbo intercooler lubricant	1	\$ 60.00	\$ 60.00
6	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 275.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and refit turbo intercooler to facilitate repair. To perform pressure test and check system functionality.	0.75	\$ 150.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
5	Supply spray paint material and necessary items to respray front bumper, o/s front door, o/s step panel and other affected area / panel.	5	\$ 1,000.00
Total labour			\$ 2,300.00

Estimate Grand Total	\$ 12,967.30
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: