

ASS. REC. BY:

REF: 1-02 / 20007783/He

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 824K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 8/24 Person Contacted: _____ Vehicle: IN / OUT

Veh No: 8642B Yr Regn: 09, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Avante c.c. 1591

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 209820 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM1HDU41BLAU 862227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / AIRlm or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. 2 mm L/Bal. 2 mm

D.O.A. 26/7/20 D.O.I. 28/7/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Frt & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ EST not ready

2018 / 11 Rm 829500 confirmed

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

KUM CHEW MOTOR WORKSHOP

60, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg

GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

M/S FIRST CAPITAL INSURANCE LTD
 36, ROBINSON ROAD #16-01
 CITY HOUSE, SINGAPORE 068877.
 cwsmotorclaims@msfirstcapital.com.sg

Attention : Motor Claim Department

Contact : 62222311/65073848(C) 65073852 Fax No. : 62244174/65073849(C)

Estimate : ES004999

Date : 06/08/2020

Vehicle Num. : SJS 8642 B

Make/Model : HYUNDAI AVANTE-2009

Chassis/Eng# : KMHU41BLAU862227/G4FC9U72288

Accident Date : 26/07/2020

Claim No. :

Reference : KC/TP8642/2007-11

Policy No. :

Not Authorised

41 Sng @ 2950p

Heavy After Paint

5 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | |
|-----|--------|--------------------------------|
| 1. | 1 PC | LIST ITEMS : |
| 2. | 1 PC | FRT BUMPER |
| 3. | 1 PC | FRT BUMPER SIDE RETAINER - RH |
| 4. | 1 PC | FRT BUMPER REINFORCEMENT |
| 5. | 1 PC | FRT BUMPER BRACKET |
| 6. | 1 PC | FRT BUMPER FOG LAMP COVER - RH |
| 7. | 1 PC | FRT BUMPER LOWER GRILLE |
| 8. | 1 PC | FRT HEADLAMP - RH |
| 9. | 1 PC | FRT FENDER - RH |
| 10. | 12 PCS | FRT FENDER DUST COVER - RH |
| 11. | 1 PC | FRT FENDER DUST COVER CLIPS |
| 12. | 1 PC | FRT SPORT RIM - RH |
| 13. | 1 PC | FRT SUSPENSION - RH |
| 14. | 1 PC | FRT LOWER ARM - R/H |
| 15. | 1 PC | FRT KNUCKLE - R/H |
| 16. | 1 PC | FRT KNUCKLE BEARING - RH |
| 17. | 1 PC | FRT STABILIZER BAR |
| 18. | 1 PC | FRT STABILIZER BAR JOINT - R/H |
| 19. | 1 PC | FRT WIPER TANK |
| | | WIPER TANK MOTOR |

List Total S\$:

20.00% Discount S\$:

- | | | |
|----|------|----------------------|
| 1. | 1 PC | SPECIAL NETT ITEMS : |
| | | FRT TYRE - RH |

Special Nett Total S\$:

Bu	461.40	✓
Di	18.70	✓
R	254.00	X
cat	29.80	✓
Sn	30.00	X
in	47.00	✓
my cat	480.00	✓
R	521.20	✓
Di	48.00	✓
3.00	36.00	✓
Di	631.20	3205
Di	234.60	✓
R	310.60	✓
R	309.00	✓
R	136.00	✓
Sn	183.80	X
in	69.10	X
Di	58.30	✓
cat	54.70	✓

3,913.40

782.68

3,130.72

Sn 180.00 X

180.00

CONTINUE / ...

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

M/S FIRST CAPITAL INSURANCE LTD
 36, ROBINSON ROAD #16-01
 CITY HOUSE, SINGAPORE 068877.
 cwsmotorclaims@msfirstcapital.com.sg

Attention : Motor Claim Department

Contact : 62222311/65073848(C) 65073852 Fax No. : 62244174/65073849(C)

Estimate : ES004999

Date : 06/08/2020
 Vehicle Num. : SJS 8642 B
 Make/Model : HYUNDAI AVANTE-2009
 Chassis/Eng# : KMHU41BLAU862227/G4FC9U72288
 Accident Date : 26/07/2020
 Claim No. :
 Reference : KC/TP8642/2007-11
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TOWING CHARGE

85.00 *50d*

TO PULL, KNOCK ON FRT ACCIDENT PORTION & CHANGE THE ABOVE PARTS.

750.00 *500d*

TO SPRAY & PAINT ON FRT ACCIDENT PORTION.

850.00 *400d*

TO ANTI-RUST AFFECTED AREAS.

50.00 *30d*

TO DISMANTLE & REPLACE UNDERCARRIAGE.

250.00 *180d*

TO CHECK WIRING FUNCTION.

50.00 *20d*

TO COMPUTER FOUR WHEEL ALIGNMENT.

150.00 *60d*

Labour Total S\$:

2,185.00

SingDollars : Five Thousand Four Hundred Ninety-Five & Cents Seventy-Two Only

Total S\$: 5,495.72

=====

KUM CHEW MOTOR WORKSHOP

KUM CHEW MOTOR WORKSHOP

160, Sin Ming Drive
Sin Ming Autocity #05-08, Singapore 575722.
TEL: 6453 6256, 6456 3715 FAX: 6455 7754
Email:kumchew1@singnet.com.sg

Date : 21/08/2020

M/s First Capital Insurance Pte Ltd
36, Robinson Road #16-01
City House
Singapore 068877.

Dear Sir/Madam

ACCIDENT INVOLVING SJS 8642 B & SHB 3090 P ON 26/07/2020.

We act for Mr Kwek Lew Tat Samuel, the owner of motor vehicle No. SJS 8642 B in the abovementioned matter.

We are instructed that you are the insurer of motor vehicle SHB 3090 P at the material time. We are further instructed that the accident caused by your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our clients have been put to loss and expense, particulars of which are as follow:-

We quantify our client's claim as follows:-

Cost of Repair (inclusive of GST)	: \$3156.50
Loss of Use (8 Days x \$100.00)	: \$ 800.00(include 1day PRI, 31/7/20 PH & 2/8/20 Sunday)
	<u>\$3956.50</u>

The following supporting documents are enclosed herewith:-

1. Invoice from Kum Chew Motor Workshop;

Thank you.

Yours faithfully,

.....
Mdm Lim