



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

CHINA TAIPING INSURANCE
3 Anson Rd
#16-00 springleaft Tower
Singapore 079909

Vehicle number SLZ8827A
Make / Model MINI/ ONE 1.6
Chassis number WMWSR32050T805596
Accident date 27 July 2020
Reference 2007-29

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER	LKK Auto Consultants hence notify the Repairer of the following: 720.00 RY
2	FRONT BUMPER RETAINER	• To resurvey before/after spray painting 98.00 X
1	FRONT BUMPER REINFORCEMENT	• To display damaged part(s) during resurvey 624.00 X
1	FRONT BUMPER TOW COVER	• Parts prices are subject to confirmation 71.00 X
1	TRIM STRIP CHROME	• Third party survey is on a "Without Prejudice" basis 221.00 CM ✓
1	FRONT FOG LAMP RH	• No illegal modification(s) is allowed 312.00 X UN ✓
1	FOG LAMP COVER RH	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 62.40 X UN ✓
1	FRONT GRILLE	Acknowledged by Repairer Signature: 392.50 P. Cua ✓
1	FRONT GRILLE CHROME MOULDING (UPPER)	181.60 X UN ✓
1	FRONT GRILLE CHROME MOULDING (LOWER)	181.60 X UN ✓
1	BONNET	1260.00 bt ✓
1	BONNET EMBLEM	81.60 ad ✓
1	FRONT HEADLAMP RH	792.00 X UN ✓
1	FRONT HEADLAMP RING RH	79.20 X UN ✓
		5076.90
		Less 5 % 253.84
		Subtotal 4823.06
		Balance C/F
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	FRONT BUMPER CLIP	50.00 X UN ✓
1 SET	FRONT GRILLE CLIP	40.00 X UN ✓
	3M sticker nec	700.500
		Subtotal 90.00
		Balance C/F 4913.06
LABOUR AND MISCELLANEOUS CHARGES		
		Balance B/F 4913.06
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30 ✓
2	PANEL BEATING ON AFFECTED AREAS	800.00 400 ✓
3	SPRAY PAINTING ON AFFECTED AREAS	800.00 400 ✓
4	APPLY ANTI RUST ON AFFECTED AREAS	100.00 30 ✓
5	REMOVE AND RESTICK STICKER ON AFFECTED AREA	400.00 200 ✓
		Subtotal 2960.00
		Grand total 7873.06

1955.10

1857.34

500.

1060-

Tanfer 974544
- WP Lampson
Resurvey after repair

03 days - 29/7/20
tanh@11kanto.com



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

CHINA TAIPING INSURANCE
3 Anson Rd
#16-00 springleft Tower
Singapore 079909

Vehicle number	SLZ8827A
Make / Model	MINI/ ONE 1.6
Chassis number	WMWSR32050T805596
Accident date	27 July 2020
Reference	2007-29

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER LOWER GRILLE	244.90 am ✓
1	FRONT BUMPER LOWER GRILLE CHROME	176.60 int ✓
		421.50
Less 5 %		21.07
Subtotal		400.43
Balance C/F		400.43 ✓

[Signature] 30/7

1857.34
500
1060
400.43

3817.77
1/5 @ 3050.
03 days.