

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

28-Jul-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1076 J

1 pc	o/s mirror Assy		\$ 590.00 <i>Rx</i>
		Less 10%	\$ 59.00
			<u>\$ 531.00</u>
	Sundry		\$ 50.00 ^x NN
	To dismantle and replace the o/s wing mirror assy		\$ 150.00 / ^{oo}
	To putty and spray painting on o/s mirror assy		<u>\$ 150.00 /^{oo}</u>
			<u>\$ 881.00</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.**

Taufik 97495749
WP
29/7/20 @ 240pm
1 days
Resurvey after repair
taufik@lkk.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: