



ALLSWELL MOTOR TRADERS

25, Defu Lane 9, Singapore 539266

GST Reg No.: 53192889J

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

(3rd Party Claim Against *ATG Incurred sum \$40560*)

POA: 27.07.2020

Repair Estimate

Vehicle No. : *SMAA079M*
Make & Model : *VOXY hybrid 1.8 x CVT*

Submitted by : *Ben*
COE Expiry : *05.06.2028*

S/No	Part Description	Qty	Price	Unit Price	Disposition by
01	RH fender / <i>buc</i>	01	<i>\$729.00</i>	630	
02	Front bumper X <i>Repair</i>	01	<i>\$1719.00</i>	X	
03	Hybrid logo / <i>MC</i>	01	<i>\$65.00</i>	47.9	
				677.9	
			-25%	508.43	
	<i>Special net</i>				
01	Clips & retainers studs <i>\$150 / pkt / MC</i>	01	<i>\$150.00</i>	30	
	<i>Labour Description</i>				
01	Dismantle / Assembly of fender / bumper panel knocking on support panel	01	<i>\$800.00</i>	<i>400</i>	400
02	Spray painting of all parts affected including polish & wash	01	<i>\$800.00</i>	<i>500</i>	
				1438.43	

3 x 2 days

part by part

before paint photos

Ben Qiang - 82880282

27/7/2020

Note: If any the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: