

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 04 Aug 2020

Preliminary Advice

Vehicle No	: SLD2982P	Accident Date	: 13/07/2020
Make	: VOLVO S60	Policy No.	: DMPCSNW00055642003
Assignment Date	: 29/07/2020	Excess	: S\$0.00
Date of Inspection	: 04/08/2020	Est. Duration of Repair	: 4
Inspection At	: ALAN'S UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE, #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,033.62
Revised Amount	:S\$	4,099.52
Check Items (Estimated)	:S\$	179.10
Total	:S\$	4,278.62

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	71,000.00
COE / PARF Rebate	:S\$	47,539.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,461.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repairer unable to provide cost price, will repair this vehicle on list price under part by part as no 2nd hand parts.