

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cecilia Low

Date: 30 Jul 2020

**Preliminary Advice**

Vehicle No	: SGD8688J	Accident Date	: 27/04/2020
Make	: VOLKSWAGEN SHARAN	Policy No.	: DMPCSNW00072222000
Assignment Date	: 29/07/2020	Excess	: S\$0.00
Date of Inspection	: 30/7/2020	Est. Duration of Repair	: 5
Inspection At	: VOLKSWAGEN GROUP SINGAPORE PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,396.78
Revised Amount	:S\$	13,160.09
Check Items (Estimated)	:S\$	1,819.60
Total	:S\$	14,979.69

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	68,893.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,107.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :