

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SLG 8428T  
 TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877  
 TEL: 65073848 FAX: 65073849  
 ATTN: Motor Claim Department

Estimate No: ES2090564/YISHUN  
 Date: 03 Aug 2020  
 Policy No: 5084913196-03  
 Veh Reg No: SLG8428T  
 Make/Model: HONDA HONDA VEZEL  
 1.5X A  
 Chassis No: RU11204321  
 Engine No: L15B4404321  
 Reg. Date: 14/10/2016

WS Ref: TP/FC  
 Claim Type: Third Party  
 Accident Date: 26/07/2020  
 TP Veh Reg No: SHA4776T

*Not Authorized*  
*L15Bp & 2750h*  
*Resurvey After Repair*  
*4 days*

## Estimate Repair Cost to Vehicle No :SLG8428T

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>List Price</b>				
1 FRONT BUMPER <i>801.70</i>	801.70	1 PC	801.70	<input checked="" type="checkbox"/>
2 FRONT BUMPER LH SIDE RETAINER	17.00	1 PC	17.00	<input checked="" type="checkbox"/>
3 FRONT BUMPER CLIPS	3.90	6 PCS	23.40	<input checked="" type="checkbox"/>
4 FRONT BUMPER LH FOG LAMP GARNISH	45.00	1 PC	45.00	<input checked="" type="checkbox"/>
5 FRONT LH FENDER WHEEL GARNISH	153.00	1 PC	153.00	<input checked="" type="checkbox"/>
6 LH HEADLAMP <i>(1110)</i>	1,840.50	1 PC	1,840.50	<input checked="" type="checkbox"/>
7 FRONT BUMPER REINFORCEMENT	360.80	1 PC	360.80	<input checked="" type="checkbox"/>
8 FRONT GRILLE	351.80	1 PC	351.80	<input checked="" type="checkbox"/>
			3,593.20	
		Less 20%	718.64	2,874.56
<b>Labour</b>				
9 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMP,TO KNOCK & REPAIR FRT LH FENDER,FRT SUPPORT PANEL & REALIGN THE SAME	500.00	1 LA	500.00	<i>400</i>
10 PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT,FRT LH FENDER,FRT SUPPORT PANEL	700.00	1 LA	700.00	<i>500</i>
			1,200.00	1,200.00

Total S\$ 4,074.56

Add GST @ 7% 285.22

Total Amount Payable S\$ 4,359.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE