

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

not Authorized

2/1/20

30/7/20

1/5 @ 9800/

take photo After repair
12 days

M/S : AIG INSURANCE

Estimate No : M001683

Date: : 29/07/2020

Veh Reg No : SLR4523U

Make/Model : MAZDA3

Chassis No : JM6BN22A8H0162240

Engine No: P520454474

Reg. Date : 16/08/2017

PAGE:2/3

ATTN : Motor Claim Department

Your Ref No: : SLR4523U

Claim Type : THIRD PARTY

Accident Date : 24/07/2020

Estimate Repair Cost to Vehicle No : SLR4523U

S/N	Description	Quantity	Unit	Price	Amount
	<u>LIST PRICE</u>			<u>S\$</u>	<u>S\$</u>
27	Rear Bumper Reflector - LH	1	PCS	56.00 17	56.00 X
28	Rear Bumper Towing Cover	2	PCS	17.80 mis	35.60 ✓
29	Rear Bumper Centre Bracket	1	PCS	35.60 ns	35.60 X
30	Rear Bumper Lower Clips	4	PCS	5.50 nu	22.00 ✓
31	Rear Exhaust Silencer	1	Set	654.00 n	654.00 X
32	Rear Exhaust Rubber	2	PCS	48.00 su	96.00 X
33	Rear Exhaust Top Heater Cover Plate	1	PCS	112.00 Best	112.00 ✓
34	Front Support Panel	1	PCS	569.70 n	569.70 X
35	Front Top Panel	1	PCS	110.20 n	110.20 X
36	Front Top Garnish	1	PCS	368.40 20/12	368.40 ✓
37	Front Top Garnish Clipse	6	PCS	5.50 n	33.00 X
38	Front Top Garnish Inner Support	1	PCS	298.40 17	298.40 X
39	Front HeadLamp	2	PCS	773.70 cre	1547.40 ✓
40	Front Grille	1	PCS	450.40 cre	450.40 ✓
41	Front Grille Inner Bracket 38x22x76	2	PCS	60.40 cre	120.80 ✓
42	Front Grille Moulding	2	PCS	176.70 cre	353.40 ✓
43	Front Grille Logo	1	PCS	58.00 scr	58.00 ✓
44	Front Bumper	1	PCS	925.20 20/12	925.20 ✓
45	Front Bumper Reinforcement 444.50	1	PCS	565.10 2nd	565.10 ✓
46	Front Bumper reinforcement Garnish	2	PCS	42.20 10/11	84.40 ✓
47	Front Bumper Side Retainer	2	PCS	39.70 n	79.40 X
48	Front Bumper Towing Cover - RH	1	PCS	30.40 n	30.40 X
49	Front Bumper Lower Cover - RH	1	PCS	18.00 mis	18.00 ✓
50	Front Number Plate Support	1	PCS	52.20 10/11	52.20 ✓

10862

TOTAL	12726.20	14060.70
Discount 20%	10180.96	11248.56

Not Authorized
30/7/20
1/4/5
Who photo Attached

M/S : AIG INSURANCE

Estimate No : M001683

Date: : 29/07/2020

Veh Reg No : SLR4523U

ATTN : Motor Claim Department

Make/Model : MAZDA3

Your Ref No: : SLR4523U

Chassis No : JM6BN22A8H0162240

Claim Type : THIRD PARTY

Engine No: P520454474

Accident Date : 24/07/2020

Reg. Date : 16/08/2017

Estimate Repair Cost to Vehicle No : SLR4523U

PAGE:1/3

S/N	Description	Quantity	Unit	Price	Amount
	<u>LIST PRICE</u>			<u>S\$</u>	<u>S\$</u>
1	Rear Boot	1	PCS	1004.00	1004.00 ✓
2	Rear Boot Hinges	1	PCS	152.00	152.00 X
3	Rear Boot Emblem (Mazda3)	1	PCS	55.00	55.00 ✓
4	Rear Boot Emblem (SkyActiv)	1	PCS	52.00	52.00 ✓
5	Rear Boot Centre Logo	1	PCS	77.00	77.00 ✓
6	Rear Boot reflector Lamp - LH	1	PCS	278.00	278.00 ✓
7	Rear Boot Inner Cover	1	PCS	264.00	264.00 X
8	Rear Boot Inner Cover Clipse	1	PCS	5.50	5.50 X
9	Rear Boot Lock	1	PCS	185.00	185.00 ✓
10	Rear Boot Lock Catch	1	PCS	48.00	48.00 X
11	Rear Boot Rubber	1	PCS	135.00	135.00 ✓
12	Rear Fender - LH 1129.30	1	PCS	1233.00	1233.00 ✓
13	Rear Fender Inner Side Garnish	1	PCS	268.00	268.00 X
14	Rear Fender Inner Side Garnish Clipse	12	PCS	5.50	66.00 X
15	Rear Tools Sponge Tray	1	PCS	264.10	264.10 ✓
16	Rear Windscreen Moulding	1	PCS	77.00	77.00 ✓
17	Rear Tail Lamp - LH	1	PCS	534.00	534.00 ✓
18	Rear Tail Lamp Clipse - LH	3	PCS	8.50	25.50 X
19	Rear Tail Lamp Panel - LH	1	PCS	126.00	126.00 ✓
20	Rear End Panel	1	PCS	530.00	530.00 ✓
21	Rear End Panel Top Garnish	1	PCS	120.00	120.00 ✓
22	Rear End Panel Top Garnish Clipse	4	PCS	5.50	22.00 X
23	Rear Bumper 1074.60	1	PCS	1127.00	1127.00 ✓
24	Rear Bumper Reinforcement 537.30	1	PCS	563.00	563.00 ✓
25	Rear Bumper Side Retainer	2	PCS	38.00	76.00 ✓
26	Rear Bumper Dust Cover - LH	1	PCS	98.00	98.00 ✓