

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# GZ713G

Model:

NISSAN

Accident Date : 29/7/2020

(23/11/2005)

Location : BKE TOWARDS SLE

3P:

GBJ9759J (Lonpac)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front o/s head lamp X NN	-	-	652.30
2	1 pc	Front bumper bracket ✓ BT	-	-	213.5
		Sub-Total:	0.00	0.00	865.80
			30%	0%	0%
		After Less %:	0.00	0.00	779.22
		Total:		779.22	

Chan

213.50
-10%
192.50

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

