

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Steve (LKK)

ESTIMATE OF REPAIR

Veh# GZ713G

Accident Date : 29/7/2020

Location : BKE TOWARDS SLE

Model:

NISSAN
(23/11/2005)

3P:


GBJ9759J (Lonpac)

ML 11/10
30/7/20, 2-30pm
L/S
By AL Ng - 12 days

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tail gate / OH	-	-	1,450.00
2	1 pc	Rear tail-gate aluminium cover / BT	-	800.00	-
3	50pcs	Rear tail-gate aluminium rivets / MC	-	50.00	30
4	1 pc	Rear tail-gate n/s lock / BT	-	-	123.50
5	1 pc	Rear tail-gate n/s lock lower / BT	-	-	203.20
6	2 pcs	Rear tail-gate n/s rubber stopper (LH) / ms	-	52.00	-
7	1 pc	Rear tail-gate lower panel / RO	-	-	796.70
8	3 pcs	Rear tail-gate hinges pins / BT	-	12.00	-
9	1 pc	Rear tail-gate 70KMPH emblem / MC	-	20.00	-
10	1 pc	Rear tail-gate NISSAN emblem / MC	-	106.5	-
11	1 pc	Rear n/s tail-lamp / RR	-	-	378.70
12	2 pcs	Rear n/s tail-lamp bracket / BT	-	-	163.90
13	1 pc	Rear n/s stopper / CRU	-	86.20	-
14	2 pcs	Rear o/s & n/s reverse sensor / RR	-	280.00	220
15	10pcs	Rear carriage bracket X	-	200.00	-
16	10pcs	Rear carriage screw X / BT	-	150.00	-
17	10pcs	Rear carriage rubber X / CRU	-	120.00	-
18	1 pc	Rear n/s side gate X R	-	-	1,980.60
19	5 pcs	Rear n/s tail-gate hinges pin / BT	-	20.00	-
20	1 pc	Rear n/s tail-gate aluminium cover X	-	600.00	-
21	30pcs	Rear n/s tail-gate aluminium rivets X	-	30.00	-
22	1 pc	Front o/s signal lamp / RR	-	-	385.60
23	1 pc	Front bumper / CRU	-	-	546.20
24	1 pc	Front o/s step garnish X	-	-	213.60
25	1 pc	Front o/s door sticker / MC	-	30.00	-
Sub-Total:			0.00	2556.70	6,242.00
			30%	0%	0%
After Less %:			0.00	2556.70	5617.80
Labour					
1		To dismantle damaged, straighten and welding.	1,200.00		900
2		To spray painting	1,200.00		900
3		To re-align, remove and refit rear carriage	900.00		500
4		To check wiring.	100.00		30
5		To re-seal anti-rust.	100.00		30
Sub-Total:				3,500.00	
Total:					11,674.50

Chan San Choon

Director
DipEng, AAE MIMI, MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

24 hr accident call
Acknowledged by Repairer

Signature: GZ713G ESTIMATEPg1
Date:

SAFE 8778 1999 Mobil 1

