

**ComfortDelGro Engineering Pte Ltd** (Co Reg No 199506048W)  
 59 Loyang Drive  
 Singapore 508969  
 Tel 6214 8300

Lim Tien Siong

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**  
 Singapore

→ LKK - Taufiqh  
 already surveyed  
 on 30/7 @ 1600hrs

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/07/2020
Vehicle Reg. No.:	SHC1037C	Driveable?	NO
Party At Fault:	UNKNOWN		

---

Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	01/08/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU299281	Chassis No:	KMHC851CVKU165089
Odometer:	0 KM		

  

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	3

**Present Location:** COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	1,266.32
Miscellaneous Items	11.00
Labour	720.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>1,997.32</b>
<b>+ GST 7.00% (S\$)</b>	<b>139.81</b>
<b>Nett Amount (S\$)</b>	<b>2,137.13</b>

**This claim is handled by: LIM TIEN SIONG**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

**REPAIR DETAILS**

**Reference**

Part Source: MRM-SG      Version: 1.0 (Last Synchronised: 03 Aug 2020)  
 Parts: 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's      (Price-denominated Standard List)  
 Print Code: **ComfortDelGro Engineering Pte Ltd/SHC1037C/03/08/2020 07:22**  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FL <i>Rp</i>
2	1		*REAR BUMPER CTR MOULDING	20.00	0.00	*451.25 FL <i>de</i>
3	1		*REAR BUMPER LWR MOULDING	20.00	0.00	*155.00 FL <i>de</i>
4	1		*REAR BUMPER FOGLAMP	20.00	0.00	*201.50 FL <i>xun</i>
5	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>nu</i>
6	1		*REVERSE SENSOR	0.00	0.00	*180.00 F <i>nu</i>
7	1		*REAR NO.PLATE W/TRIM COVER	0.00	0.00	*55.00 F <i>cu</i>
<b>Sub Total (\$)</b>						<b>1,524.15</b>
- List Item Discount on L Items (\$)						257.83
<b>Total Parts (\$)</b>						<b>1,266.32</b>

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC1037C/03/08/2020 07:22. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00 ✓
<b>Sub Total (S\$)</b>			<b>11.00</b>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	350.00 320
2	SPRAY PAINTING	New	250.00 200
3	R/I REVERSE SENSOR	New	120.00 30
<b>Gross Labour Cost (S\$)</b>			<b>720.00</b>

ComfortDelGro Engineering Pte Ltd/SHC1037C/03/08/2020 07:22. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfah 9744 5749  
-wp  
02 days 30/7/20 @ 4pm  
Resurvey after repair  
Tanfah @ 11am tomorrow.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: