

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO20007966/0	GUtf3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623				11-08-2020		
				SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SMM 7825T	Veh. Inspected		SMF 137D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2002262/AGC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		03/08/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	RU31268952	Colour		SILVER	
	Odometer	123011 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	R/H Rear Tyre	215/60 R16	DUNLC)P	6 mm	
	L/H Rear Tyre	215/60 R16	DUNLC)P	6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	01/08/2020	Inspec	t Date / Time	03/08/2020 (05:00 PM)	
	Survey held at	APEX MOTORING				
		25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGPORE 417800.				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					

Report Ref No. CS3/SMO20007966/GUtf3e2

Inspected By

CHUA KANG SENG
Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.