## MISCELLANEOUS ITEMS

No.	Description			Belen		
1	FRONT INNER TRIMBOARD RH CLIPS A.O.		ć	100.00 50		
2	REAR DOOR TRIMBOARD RH CLIPS NO.		\$	100.00 50		
3	SEALANT QUARTER GLASS X		\$	100.00 XM		
	Total Miscellaneous Item	s (S\$)	\$	300.00		

Total Parts	(5\$)	\$ 4,992.70
Total Labour	(\$\$)	\$ 2,350.00
Total Miscellaneous	<b>(S\$)</b>	\$ 300.00
Sub-Total	(\$\$)	\$ 7,642.70
GST 7%	(S\$)	534.99
Grand Tota	(\$\$)	\$ 8,177.68

LKK Auto Consultants hence notify
the Repairer of the following:

To resurvey before/after spray painting

To resurvey

To resurvey before/after spray painting

Resurs after repair

100

2484.88 920.00 100.00 3504.88 2803.90 413-2,800 4days

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: