

DATE: 30/7/2020

REPAIR DETAILS	
REFERENCE	
Vehicle Reg No.	: SLE1924J
Make & Model	: HYUNDAI / ELANTRA AD 1.6 GLS AT
Chassis No.	: KMHD841CMHU200451
Engine No.	: G4FGGU194339
Manufactured Year	: 2016
Labour	: REPAIRER'S
TP Vehicle Reg No.	: SHC2312B
DOA & Location	: 29/07/2020 ALONG JURONG WEST STREET 42 CARPARK
Our Ref	: SLE1924J / LIE HOCK HEE (LI FUXI)

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	RH FRT DOOR <i>bt</i>		\$ 1,868.64 <i>1350</i>
2	1	RH FRT DOOR HINGE UPPER <i>X SUC</i>		\$ 32.64
3	1	RH FRT DOOR HINGE LOWER <i>X SUC</i>		\$ 32.64
4	1	RH FRT DOOR CHECKER <i>X SUC</i>		\$ 36.72
5	1	RH FRT DOOR RUBBER <i>nee</i>		\$ 96.90
6	1	RH FRT DOOR LOCK ASSY <i>X SUC</i>		\$ 198.90
7	1	RH FRT DOOR CATCH <i>X SUC</i>		\$ 25.50
8	1	RH FRT DOOR OUTER CHROME HANDLE ASSY <i>Cra</i>		\$ 209.10 <i>197</i>
9	1	RH FRT DOOR REGULATOR <i>X SUC</i>		\$ 260.10
10	1	RH FRT DOOR REGULATOR MOTOR <i>X SUC</i>		\$ 306.00
11	1	RH FRT DOOR GLASS <i>X SUC</i>		\$ 219.30
12	1	REAR RH DOOR <i>bt</i>		\$ 1,810.50 <i>1350</i>
13	1	REAR RH DOOR HINGE UPPER <i>X SUC</i>		\$ 36.72
14	1	REAR RH DOOR HINGE LOWER <i>X SUC</i>		\$ 32.64
15	1	REAR RH DOOR RUBBER <i>nee</i>		\$ 112.20
16	1	REAR RH DOOR OUTER CHROME <i>X SUC</i>		\$ 96.90
17	1	FRT RH DOOR OUTER CHROME <i>X SUC</i>		\$ 76.50
18	1	REAR RH DOOR QUARTER GLASS <i>X SUC</i>		\$ 326.40
19	1	FRT RH DOOR INNER TRIMBOARD <i>X SUC</i>		\$ 462.57

Sub-Total (S\$) \$ 6,240.87

SAAA List Item Discount 20% (S\$) \$ 1,248.17

Sub-Total (S\$) \$ 4,992.70

LABOUR

No.	Description	Price
1	LABOUR	\$ 800.00 <i>400</i>
2	SPRAYPAINTING	\$ 800.00 <i>400</i>
3	REMOVE AND REPLACE WINDOW GLASS / QUARTER GLASS	\$ 150.00 <i>X AN</i>
4	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	\$ 300.00 <i>60</i>
5	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	\$ 300.00 <i>60</i>

Total Labour (S\$) \$ 2,350.00

3106.10
20%
2484.88

920