


MOVA

Automotive Pte Ltd

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

 Tel: (65) 6272 3892
 Fax: (65) 6270 8314

 Co. Reg. 198904033G
 GST Reg. M2-008864-2

Estimate

24/07/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SJZ133U

Veh Model :- TOYOTA ESTIMA AERAS 2.4A

Estimate# :- CK420835

Claim # :- TP/CK 138639

ACC. Date :- 18/07/20

Terms :- C.O.D Days

Remarks :- MFR 20 DEC 2013 (2013)

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR WINDSCREEN MOULDING <i>nee</i>	1 PC	107.00	107.00
2.	TAILGATE <i>bt</i>	1 PC	1,753.00	1,753.00
3.	TAILGATE LOGO <i>nee</i>	1 PC	72.00	72.00
4.	TAILGATE EMBLEM - ESTIMA <i>nee</i>	1 PC	49.00	49.00
5.	TAILGATE EMBLEM - AERAS <i>nee</i>	1 PC	58.00	58.00
6.	TAILGATE LOCK <i>? xsv</i>	1 PC	371.00	371.00 X
7.	TAILGATE RUBBER <i>nee</i>	1 PC	490.00	490.00
8.	REAR BUMPER <i>de</i>	1 PC	635.00	635.00
9.	REVERSE SENSOR CTR RH <i>? aw</i>	1 PC	490.00	490.00
10.	REAR BUMPER CLIPS <i>nee</i>	10 PC	5.00	50.00
11.	REAR BUMPER SIDE RETAINER LH <i>xsv</i>	1 PC	58.00	58.00 X
12.	REAR BUMPER SIDE RETAINER RH <i>xsv</i>	1 PC	58.00	58.00 X
13.	REAR BUMPER SPONGE <i>? xsv</i>	1 PC	79.00	79.00 X
14.	ANTTENA SENSOR <i>? aw</i>	1 PC	196.00	196.00
15.	END PANEL TOP GARNISH <i>de</i>	1 PC	308.00	308.00
16.	END PANEL <i>bt photo</i>	1 PC	755.00	755.00
17.	FLOOR PANEL - REPAIR	1 PC		

LIST TOTAL S\$

5,529.00

25% DISCOUNT S\$

-1,382.25

4,146.75

SPECIAL NET ITEMS :

 1. SEALANT *nee* 1 PC 40.00 40.00 ✓

SPECIAL NET TOTAL S\$

40.00

LABOUR :

TO REMOVE & TRANSFER REAR WINDSCREEN GLASS

120.00 ✓

 TO REMOVE & INSTALL REVERSE SENSOR & DIAGNOSE
 FUNCTION

60 80.00 ✓

 TO CUT OFF END PANEL. TO REMOVE & REPLACE
 DAMAGED ITEMS, REALIGN CONNECTION.

600 700.00 ✓

TO REMOVE & REFIT REAR LUGGAGE COMPARTMENT

80 150.00 ✓

TO APPLY BODY JOINT SEALANT ON CUTTING AREAS

60 80.00 ✓

TO RUST PROOF ON REPAIRED AREAS

60 80.00 ✓

TO SPRAY PAINT IN REPAIRED AREAS

600 700.00 ✓

TO RESET POWER TAILGATE FUNCTION

60 80.00 ✓

LABOUR TOTAL S\$

1,990.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

24/07/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 138639

Veh # :- SJZ133U

Veh Model :- TOYOTA ESTIMA AERAS 2.4A

Estimate# :- CK420835

Claim # :-

ACC. Date :- 18/07/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 6,176.75

GST @ 7 % 432.37

AMOUNT DUE S\$ 6,609.12

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
6 days
4/5
05/08/2020 @ 1420
Resurvey after repair