

ASS. REC. BY:

REF:

AIG/ 20007985/kk

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLO 9765DYr Regn: 07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 1 Honda Jazzc.c. 1318Colour: M. Maroon

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 74003

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK 38506X 240592Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: _____

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 31/7/20D.O.I. 3/8/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

olsm & ulc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/8 21 Sup @ 3300 Confirmed

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLD9765D
 TP/AIG

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES2090565/YISHUN
 Date: 03 Aug 2020
 Policy No: 20-ML000325-R00
 Veh Reg No: SLD9765D
 Make/Model: HONDA HONDA JAZZ
 1.3 CVT ABS D/AIRBAG
 2WD
 Chassis No: JHMGK3850GX240592
 Engine No: L13B11010300
 Reg. Date: 01/07/2016

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 31/07/2020
 TP Veh Reg No: SJY241X

Not Withheld

1/1 Smp @ 3300

Refuse After Pain

6 days

Estimate Repair Cost to Vehicle No :SLD9765D

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT RH FENDER	435.60	1 PC	435.60	—
2 FRONT RH FENDER INNER SHIELD	71.50	1 PC	71.50	—
3 FRONT RH FENDER INNER SHIELD CLIPS	3.90	6 PCS	23.40	—
4 FRONT RH DOOR	1,050.20	1 PC	1,050.20	—
5 FRONT RH DOOR FRAME STICKER	20.20	1 PC	20.20	—
6 FRONT RH DOOR INNER RUBBER	83.10	1 PC	83.10	—
7 FRONT RH DOOR TOP HINGE	40.10	1 PC	40.10	—
8 FRONT RH DOOR BOTTOM HINGE	40.10	1 PC	40.10	—
9 FRONT RH SHOCK ABSORBER	310.90	1 PC	310.90	—
10 FRONT RH KNUCKLE ARM	280.30	1 PC	280.30	—
11 FRONT RH WHEEL BEARING	168.00	1 PC	168.00	—
12 FRONT RH LOWER ARM	160.10	1 PC	160.10	—
			2,683.50	
		Less 20%	536.70	2,146.80
Special Net				
13 FRONT RH SPORT RIM	450.00	1 PC	450.00	450.00
Labour				
14 REMOVE & REFIX FRT BUMPER ASSY,FRT RH FENDER,FRT RH DOOR & ATTACHMENT,SIDE MIRROR,KNOCK & REPAIR FRT RH W/SCREEN PILLAR & REALIGN THE SAME	800.00	1 LA	800.00	800.00
15 REMOVE & REFIX SEAT,CARPET,SAFETY BELT	100.00	1 LA	100.00	100.00
16 REMOVE & REFIX FRT RH UNDER CARRIAGE AND CHECK STEERING & DRIVE SHAFT	200.00	1 LA	200.00	200.00
17 PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR,RH ROCKER PANEL,FRT RH SIDE MIRROR,FRT RH FENDER,FRT RH DOOR,FRT BUMPER & ALL AFFECTED AREAS	900.00	1 LA	900.00	900.00
18 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	60.00
19 RUSTPROOFING	60.00	1 LA	60.00	60.00
			2,120.00	2,120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ 4,716.80
 Add GST @ 7% 330.18
 Total Amount Payable S\$ 5,046.98

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 288C

Vehicle Details

Vehicle No.: SLD9765D
Vehicle to be Exported: Yes
Intended Deregistration Date: 01 Aug 2020
Vehicle Make: HONDA
Vehicle Model: JAZZ 1.3 CVT ABS D/AIRBAG 2WD
Primary Colour: Purple
Manufacturing Year: 2016
Engine No.: L13B11010300
Chassis No.: JHMGK3850GX240592
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$15,707.00
Original Registration Date: 01 Jul 2016
First Registration Date: 01 Jul 2016
Transfer Count: 0
Actual ARF Paid: \$10,707.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Jun 2026
PARF Rebate Amount: \$8,030.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$47,020.00
COE Rebate Amount: \$27,807.00
Total Rebate Amount: \$35,837.00

The information contained herein is correct as at 01 Aug 2020

OK