



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:WINNIE

Ref: CC4/ASM20007991/Bpa3q2
Date: 15/12/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 5661D	Veh. Inspected	SJF 749Z
Policy No.	GA496073	Coverage (\$)	0.00
Claim No.	S0M02R7W	Excess (\$)	0.00
Assign From		Assign Date	31/07/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT 1.5 RS M	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GE81017125	Colour	PURPLE
Odometer	245871 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/07/2020	Inspection Date	03/08/2020
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**