

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA	DATE	: 30/07/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SJT5965J		<i>Khanchana</i>
MODEL	: TOYOTA COROLLA ALTIS 1.6A		
CHASSIS NO			
ACCIDENT DETAILS	DATE : 29-Jul-20		
	TIME : 15:40HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BONNET <i>Dented</i>	1	\$ 655.30	\$ 655.30	✓
2	BONNET HINGE <i>Neu</i>	2	\$ 88.00	\$ 176.00	✗
3	BONNET LOCK <i>Dang</i>	1	\$ 160.00	\$ 160.00	✓
4	BONNET LOCK BRACE PANEL <i>Bent</i>	1	\$ 110.00	\$ 110.00	✓
5	FRONT BUMPER <i>Distorted</i>	1	\$ 450.00	\$ 450.00	✓
6	FRONT BUMPER SIDE RETAINER <i>Neu</i>	2	\$ 62.40	\$ 124.80	✓
7	FRONT BUMPER WEATHERSTRIP <i>lit</i>	1	\$ 90.00	\$ 90.00	✓
8	FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 388.40	\$ 388.40	✓
9	FRONT BUMPER FOG LIGHT <i>LH cracked</i>	2	\$ 190.00	\$ 380.00	190
10	FRONT BUMPER FOG LIGHT COVER <i>Missing</i>	2	\$ 80.00	\$ 160.00	✓
11	FRONT BUMPER TOP GRILLE <i>crack</i>	1	\$ 399.50	\$ 399.50	✓
12	FRONT BUMPER LOWER GRILLE <i>Missing</i>	1	\$ 160.00	\$ 160.00	✓
13	FRONT BUMPER LOGO <i>Neu</i>	1	\$ 69.30	\$ 69.30	✓
14	HEADLAMP <i>Cracked</i>	2	\$ 455.20	\$ 910.40	✓
15	HEAD LAMP LOWER BRACKET <i>Neu</i>	2	\$ 66.40	\$ 132.80	✗
16	FRONT FENDER <i>Repair</i>	2	\$ 466.70	\$ 933.40	✗
17	FRONT FENDER EMBLEM 'VVTI' <i>Neu</i>	2	\$ 65.20	\$ 130.40	✓
18	FRONT FENDER INNER COWLING <i>Neu</i>	2	\$ 180.00	\$ 360.00	✗

19	SUPPORT PANEL	Buckled	1	\$ 950.20	\$ 950.20	✓ 770.80
20	HORN	Ne m	2	\$ 95.20	\$ 190.40	x
21	AIR CONDENSOR	Best	1	\$ 1,395.00	\$ 1,395.00	✓ 1295
22	AIR CONDENSOR MOUNTING	ne m	2	\$ 18.00	\$ 36.00	x
23	AIR CON PIPE (H)	gate m	1	\$ 370.00	\$ 370.00	x
24	AIR CON PIPE (L)		1	\$ 370.00	\$ 370.00	x
25	RADIATOR	Dented	1	\$ 1,760.00	\$ 1,760.00	✓ 1651
26	RADIATOR TOP BRACKET	Best	2	\$ 50.00	\$ 100.00	✓
27	RADIATOR TOP MOUNTING	ne m	2	\$ 60.00	\$ 120.00	+
28	RADIATOR BOTTOM MOUNTING	Ne m	2	\$ 60.00	\$ 120.00	x
29	RADIATOR FAN COWLING	could	1	\$ 276.00	\$ 276.00	✓
30	FRONT WIPER WASHER TANK (UPPER)	?	1	\$ 176.00	\$ 176.00	x
31	FRONT WIPER WASHER TANK (LOWER)	?	1	\$ 295.00	\$ 295.00	x
32	FRONT WIPER WASHER TANK MOTOR		1	\$ 235.00	\$ 235.00	x.

Radiator Fan cowling motor 1 TOTAL PRICE ²³⁰ \$ 12,183.90
 LESS 25% \$ 3,045.98
 SUB TOTAL PRICE \$ 9,137.93

8309 Paid
 624067

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE	could	1 \$ 50.00	\$ 50.00	✓
2	FRONT BUMPER CLIPS(SET)	on	1 \$ 20.00	\$ 20.00	✓
3	FRONT BUMPER UNDER COVER GARNISH CLIP(SET)	ne m	1 \$ 20.00	\$ 20.00	✓
4	FRONT GRILLE CLIP	ne m	1 \$ 20.00	\$ 20.00	✓
5	FRONT FENDER COWLING CLIPS(SET)	Ne m	1 \$ 20.00	\$ 20.00	✓
6	HEADLAMP CLIP(SET)	ne m	1 \$ 20.00	\$ 20.00	✓
7	RADIATOR COOLANT	on	1 \$ 80.00	\$ 80.00	40

Battery at TOTAL \$ 20.00
 \$ 250 \$ 250 180.

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	8w	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	8w	
3	WIRING CHECK	\$ 150.00	30	
4	REFOCUS HEADLAMP BEAM	\$ 60.00	x	
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60	
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60	

1750

TOTAL: \$ 4,010.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,157.93
TOTAL LABOUR COST : \$ 4,010.00
TOTAL REPAIR COST : \$ 13,167.93

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Ly
t/s 03/08/20-
06 Days.

Total: 8340 67.

t/s: G-6K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: