Elaine (LKK Auto)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

To: kennylim@lonpac.com Cc: MT_Claim_SG; 'SUR'; 'Huey Yon (LKKAuto)' Subject: Pre-Repair Survey Report of Vehicle GBK 639B Ref: 20/20/VC05/023509 **Attachments:** LKK photo.pdf; LKKPreRepairInspection.pdf; LPC2-LKKInvoice-AC2005424.pdf Dear Kenny, Enclose Pre-Repair Survey Report of GBK 639B. Thank you. Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted. Best Regards, Elaine | Reports LKK Auto Consultants Pte.Ltd. Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com