

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB3521M      DOA: 01.08.2020  
 Make : HYUNDAI  
 Model : IONIQ

Date: ###  
 Insurance: NTUC  
 MVA: JUMANI

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR RH DOOR CHANNEL <i>art ✓</i>	<i>25%</i>	83.40	104.25
1	REAR RH DOOR CHANNEL RUBBER <i>art ✓</i>		36	45
1	REAR RH DOOR DELTA MOULDING <i>art ✓</i>		24	30
<b>SUB TOTAL</b>		<i>25%</i>	- 143.40	179.25 \$-
<b>LESS 20%</b>				\$-
<b>LESS 25%</b>				\$-
<b>DISCOUNTED TOTAL</b>				\$-
<div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: 80%;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer                      Signature:                      Date:</p> </div>				
<b>Labour Charge</b>				
	PANEL BEATING			\$700.00 <i>480</i>
	SPRAYPAINT			\$300.00 <i>200</i>
	TRANSFER DOOR PARTS		<i>680</i>	\$120.00 <i>x n7.</i>
	<i>Taufik 97495749</i>			
	<i>wp 2/8/2005pm</i>			
	<i>p/p Resurvey after repair.</i>			
	<i>taufik@lkkauto.com</i>			
	<i>(2) 3 days</i>			
<b>TOTAL LABOUR</b>			<i>9823.40</i>	<b>\$1,120.00</b>
<b>ESTIMATE TOTAL</b>			<i>2 days #</i>	<b>\$1,120.00</b>
				1263.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.