



# QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67  
 AUTOBAY, SINGAPORE 417883  
 HP: 96709191 FAX: 66840767

MS First Capital Insurance Ltd  
 6 Raffles Quay  
 #21-00  
 Singapore 048580

Date: 4 August 2020

*Not Authorized*  
*LH*  
*4/8/20*  
*2/5 \$4650*  
*The photo taken 10 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No official modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Accident on 31/07/2020 involving vehicles SGW2770T & SH9490S  
 along Punggol Road Junction**

**Estimate cost of repair to vehicle SGW2770T Honda Airwave**

|        |                               |            |              |    |
|--------|-------------------------------|------------|--------------|----|
| 1 pc.  | bonnet                        | BUC        | \$ 816.90    | ✓  |
| 1 pc.  | bonnet chrome moulding        | SCR        | \$ 285.60    | ✓  |
| 2 pcs. | bonnet hinges @\$65.00        | R          | \$ 130.00    | X  |
| 1 pc.  | bonnet insulator              | D.S        | \$ 142.50    | ✓  |
| 1 pc.  | front grille                  | BRD        | \$ 240.50    | ✓  |
| 1 pc.  | front grille base             | BRD        | \$ 190.60    | ✓  |
| 1 pc.  | front grille logo             | M.S        | \$ 38.00     | ✓  |
| 1 pc.  | front support panel           | D.S        | \$ 665.60    | ✓  |
| 1 pc.  | headlamp lh                   | BRD        | \$ 868.00    | ✓  |
| 1 pc.  | headlamp lower bracket lh     | CNE        | \$ 65.00     | ✓  |
| 1 pc.  | front bumper                  | D.S        | \$ 981.00    | ✓  |
| 1 pc.  | front bumper center grille    | TORN       | \$ 142.50    | ✓  |
| 1 pc.  | front bumper reinforcement    | D.S        | \$ 280.90    | ✓  |
| 1 pc.  | front bumper side retainer lh | BRF        | \$ 32.00     | ✓  |
| 1 pc.  | front fender lh               | BUC        | \$ 661.20    | ✓  |
| 1 pc.  | front fender wheel housing lh | R          | \$ 756.60    | X  |
| 1 pc.  | front lock                    | T.M        | \$ 91.80     | ✓  |
| 1 pc.  | air-con condenser             | D.S        | \$ 1,056.00  | ✓  |
| 1 pc.  | radiator                      | holder CNE | \$ 1,422.30  | ✓  |
| 1 pc.  | radiator fan motor assy       | CNE/GRM    | \$ 525.20    | ✓  |
| 1 pc.  | front door lh                 | R          | \$ 922.30    | X  |
|        |                               |            | \$ 10,314.50 |    |
|        |                               |            | \$ 2,062.90  |    |
|        |                               |            | Less 20%     |    |
|        |                               |            | \$ 8,251.60  |    |
| 1 pc.  | front license plate (S.Nett)  | BRD        | \$ 50.00     | 40 |

*\$205.60*

## **Labour Charges:**

|                                                 |                     |      |
|-------------------------------------------------|---------------------|------|
| Towing                                          | \$ 60.00            | 50   |
| To check wiring                                 | \$ 100.00           | 30   |
| To remove & refix air-con & refill gas          | \$ 120.00           | 100  |
| To spray rust proofing                          | \$ 200.00           | 90   |
| Labour for panel beating, welding & renew parts | \$ 1,300.00         | 1000 |
| Spray painting                                  | \$ 1,250.00         | 1000 |
| <b>Total:</b>                                   | <b>\$ 11,331.60</b> |      |