

Summer Lee (LKK Auto)

From: Summer Lee (LKK Auto) <admin-d@lkkauto.com>
Sent: Tuesday, 4 August, 2020 1:48 PM
To: 'Motorsurvey'; assignments@lkkauto.com
Cc: sur@lkkauto.com
Subject: RE: OD survey assignment for YN3541R - DOA : 29/07/2020 Our Ref: NSV2000218/SG

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motorsurvey <Motorsurvey@awacgbl.com>
Sent: Tuesday, 4 August, 2020 1:35 PM
To: assignments@lkkauto.com
Cc: sur@lkkauto.com
Subject: OD survey assignment for YN3541R - DOA : 29/07/2020 Our Ref: NSV2000218/SG

The above captioned accident refers. Please conduct an "OWN DAMAGE" survey on the following:

Insured Vehicle	:	YN3541R		
Policy Number	:	BVFCSB0013691900		Account Code: B036SD0
Policy Excess	:	\$ 500	(Allied World waived \$) (Insured to pay \$)	
Voluntary Excess	:	\$	(No waiver)	
Sum Insured	:	Market Value with COE & PARF		
Make / Model	:	MITSUBISHIFM65FM1RDEA		
Name of Workshop	:	COMFORTDELGRO ENGINEERING PTE LTD		
Contact Number	:	6867 6924/ 9723 9882		
Person to Contact	:	MR WONG CHEE WEI		
Estimated Cost of repairs	:	\$ 14,358.60		

(x)	Please take photographs of the front windscreen area from inside to ascertain whether the insured vehicle is equipped with a car camera. (Compulsory)
(x)	Please revert with your preliminary survey report with photographs

Regards,

Claims Division