

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 19/20/20/VP96/304742 Date: 06th Aug 2020

Our Ref: CS1/LPM20008033/Esf3e2

M/s Lonpac Insurance Bhd

21St Flr, Bangunan Public Bank NO. 6 Jalan Sultan Sulaiman 50000 Kuala Lumpur, Malaysia

Dear Sir / Madam.

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLN 7845S

INSURED VEHICLE: WNC 8293 ACCIDENT DATE: 09/02/2020

We thank you for your instruction on 17/07/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLN 7845S from M/s CA Appraiser Pte Ltd.
- b) Polis Diraja Malaysia of Vehicles SLN 7845S, WNC 8293 and JHM 6925.
- c) Colour damaged vehicle photographs of SLN 7845S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLN 7845S

Make & Model : Mazda CX-3 Skyactiv-G 2.0 6AT 2WD SR

Year of Registration : 2017

Chassis Number : JM6DK2W7AH0127405

Engine Capacity : 1998 cc

- 2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.