

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
CHIN	A TAIPING INSUI	RANCE (S) PTE LTD	Ref : CS3/CTI20004572/	ef : CS3/CTI20004572/Qsf3e2-1	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 20-08-2020 Code: CTI			
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	YN 4458S	Veh. Inspected	SKV 7313E	
	Policy No.	DMCVSNA00007682003	Coverage (\$)	0.00	
	Claim No.	SNM20D201482C02	Excess (\$)	0.00	
	Assign From	IRENE TAY HUI PING	Assign Date	21/07/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	JTDGG20W40J002936	Colour	BEIGE	
	Odometer	109440	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	21/03/2020	Inspection Date	05/08/2020	
	Survey held at	SUPER MODERN SERVICES			
		25 KAKI BUKIT ROAD 4 #01-26 SYNERGY @ KB SINGAPORE 417800			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				