# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Tan Kah Leong Date: 06 Aug 2020

## **Preliminary Advice**

Insured Vehicle No : GBE9273U

TP Vehicle No : SMM6038E Accident Date : 01/08/2020 Make : TOYOTA C-HR HYBRID Assignment Date : 04/08/2020

Date of Inspection : 5/8/20 Est. Duration of Repair : 3

Inspection At : BW WORKSHOP SERVICES PTE LTD

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front o/s portion, and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,002.00
Revised Amount	:S\$	3,962.00
Check Items (Estimated)	:S\$	270.00
Total	:S\$	4,232.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: The above survey was conducted on a 'Without Prejudice' basis.