

BW WORKSHOP SERVICES PTE LTD

291 KAKI BUKIT AVE 1 SHUN LI

INDUSTRIAL PARK

Singapore 416080

6289 8800

workshop_admin@bw.com.sg

GST Registration No. : 201504834E

Company Registration No. 201504834E



Steve (LKK)

8322 8813

Steve chen@lkkauto.com

wrt Mr

5/8/20, 11.00pm

3 days

P/P

Ry BOL SM

Estimates**ADDRESS**

NTUC INCOME INSURANCE

CO-OPERATIVE LIMITED

ESTIMATES NO. 1203**DATE 03/08/2020****VIN NUMBER**

SMM6038E /ZYX102135966

MAKE & MODEL

TOYOTA CHR HYBRID 1.8

MILEAGE

-

ACTIVITY	QTY	RATE	AMOUNT
FRONT BUMPER / CRV	1	1,658.00	1,658.00
FRONT BUMPER SIDE RETAINER RH & LH / BR	2	150.00	300.00
FRONT FENDER RH / DD	1	1,174.00	1,174.00
FRONT FENDER RETAINER RH ? / BR	1	150.00	150.00
HEADLAMP BRACKET RH ? X NN	1	120.00	120.00 X
			Subtotal: 3,402.00
REAR BUMPER CLIPS - S/N	4	10.00	40.00
			Subtotal: 40.00
TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGH, REFIT AND TO RENEW AFFECTED PARTS.	4	200.00	800.00
			Subtotal: 800.00
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	3	200.00	600.00
TO FOCUS HEADLAMPS . TO CHECK WIRING AND LIGHTING OPERATION	1	80.00	80.00
TO CONDUCT FRONT WHEEL ALIGNMENT TEST	1	80.00	80.00
			Subtotal: 1,560.00

SUBTOTAL

5,002.00

GST TOTAL

0.00

TOTAL**SGD 5,002.00**

6772.00

NETS & Cash only.**Our Bank Details:-****Name of Bank : UOB****Account Name : BW Workshop Services Pte Ltd****Account Number :356-305-177-7****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company**Acknowledged by Repairer****Signature:****Date:**