



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7042Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,106.00	1,106.00
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
1	REAR BUMPER REFLECTOR LH	CRACKED	32.00	32.00
1	REAR BUMPER SPONGE	NOT NECESSARY	119.50	-
1	REAR BUMPER BEAM	NOT NECESSARY	428.40	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	BOOTLID MOULDING	DEFORMED	85.00	85.00
1	BOOTLID EMBLEM - CRDI	NECESSARY	27.90	27.90
1	BOOTLID EMBLEM - I40	NECESSARY	27.90	27.90
1	BOOTLID EMBLEM - HYUNDAI	NECESSARY	21.10	21.10
1	BOOTLID EMBLEM - H	NECESSARY	28.70	28.70
1	TAILLAMP LH	CRACKED	697.80	697.80
1	BOOTLID LAMP LH	NOT NECESSARY	565.60	-
	LESS 20% DISCOUNT		-677.98	-455.28
			2,711.92	1,821.12
<u>NETT ITEMS</u>				
1	BOOTLID COMFORTDELGRO (N)	NECESSARY	30.00	30.00
1	BOOTLID 65521111 (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-6.00	-6.00
			54.00	54.00
<u>LABOUR</u>				
	PANEL BEATING.		600.00	420.00
	SPRAY PAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.		40.00	30.00
	TOWING FEE. (NPA)	NOT NECESSARY	-	-
			1,140.00	850.00
GRAND TOTAL			3,905.92	2,725.12

Report Ref No. NS/INC20008075/T1qf3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,200.00
---	--	--	-----------------

Report Ref No. NS/INC20008075/T1qf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.