

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40687

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0480/2020/NS
Date : 8-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SLL 9791 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Rasul,
7 days - ok - Jy - 21 Oct 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Chan Moy Jin
Address : 33 Oxford Road
#06-13
Singapore 218816
Telephone : (HP)+65 86119811
Type of Claim : Own Damage Claims
Policy No. : 1700063167-02
Vehicle No : **SLT 235 S**
Model Code : Audi A1 SB 1.0 TFSI S TRONIC
Model / Year : Oct-17
Engine No : CHZ 507976
Chassis No : WAUZZZ8X8JB013259
Mileage : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Jul-20
Place of Accident : Along Dorset Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLT 235 S

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To dismantle lhs front door panel trim. To remove and renew lhs wing mirror assy.	S/N \$	350.00	
2	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	560.00	\$ 560.00
3	To dismantle and renew lhs front door and lhs rear door. To repair lhs sill panel, lhs B-pillar, door entrance and lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$	3,500.00	\$ 1,250.00
4	To respray lhs front door, lhs rear door, lhs B-pillar, lhs sill panel, door handle, door entrance, hinges and lhs rear fender.	\$	5,300.00	\$ 2,300.00
5	To renew lhs rear rim and carry out wheel alignment.	S/N \$	280.00	\$ 280.00
6	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,182.00	\$ 4,582.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 235 S

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT DOOR - LH	\$ 1,915.00	\$ 1,532.00
2	FRONT DOOR ATTACHMENT PARTS	\$ 126.00	
3	FRONT DOOR CATCH	\$ 84.00	\$ 66.88
4	EXTERIOR MIRROR MOUNTING - LH	\$ 434.00	\$ 363.60
5	EXTERIOR DOOR HANDLE	\$ 146.00	
6	DOOR HANDLE CAP	\$ 28.00	
7	REAR DOOR - LH	\$ 1,915.00	\$ 1,607.20
8	REAR DOOR ATTACHMENT PARTS	\$ 79.00	
9	REAR DOOR HINGE - LH UPPER	\$ 143.00	
10	REAR DOOR HINGE - LH LOWER	\$ 125.00	
11	REAR DOOR CATCH	\$ 84.00	
12	AIRBAG STICKER	\$ 23.00	
13	REAR ALUMINIUM RIM - LH	\$ 666.00	\$ 532.40
14	STONE CHIP	S/N \$ 180.00	\$ 180.00
15	SUPPLEMENTARY	\$ 42.00	\$ 33.44
16	SUNDRIES	\$ 300.00	\$ 6.88
TOTAL SPARE PARTS		: \$ 6,290.00	\$ 4,322.40
TOTAL LABOUR CHARGES		: \$ 10,182.00	\$ 4,582.00
GRAND TOTAL		: \$ 16,472.00	\$ 8,904.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

bl-22/09/20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0480/2020/NS 25-Aug-20 Glory Tan 1 OF 1 SLT 235 S Audi A1 SB 1.0 TFSI S TRONIC	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	lhs rear fender stone chip guard foil	\$ 42.00	\$ 33.44	
TOTAL		\$ 42.00	\$ 33.44	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant