

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 258 B

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
		\$	2,251.00	✓
1	FRONT BUMPER Distorted	\$	402.00	✓
2	FRONT BUMPER FIXING PARTS <i>He ne</i>	\$	70.00	✓
3	FRONT BUMPER SECURING STRIP ? <i>He ne</i>	2 \$	225.00	X
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>He ne</i>	\$	62.00	X
5	FRONT BUMPER AIR GUIDE - RH <i>He ne</i>	\$	468.00	X
6	FRONT BUMPER AIR GUIDE GRILLE - RH	\$	36.00	✓
7	FRONT BUMPER GUIDE SECTION - RH <i>Dented</i>	\$	123.00	X
8	FRONT BUMPER FOAM FILLER PIECE <i>He ne</i>	\$	795.00	?
9	FRONT BUMPER CARRIER ?	\$	TBC	?
10	FRONT PARKING AID SENSOR - FRONT OUTER ?	\$	1,048.00	✓
11	FRONT FENDER - RH <i>Dented</i>	\$	53.00	?
12	FRONT FENDER ATTACHMENT PARTS ?	\$	73.00	?
13	FRONT FENDER CLOSING ELEMENT - RH ?	\$	35.00	?
14	FRONT FENDER BRACKET - RH ?	\$	117.00	✓ <i>He ne</i>
15	FRONT FENDER BRACE - RH <i>Best.</i>	\$	49.00	?
16	DEFORMATION ELEMENT BRACKET - RH ?	\$	35.00	?
17	FRONT FENDER BRACKET ?	\$	35.00	?
18	TOP FENDER LEDGE COVER - UPPER ?	\$	16.00	?
19	TOP FENDER LEDGE COVER - LOWER ?	\$	157.00	✓
20	FRONT FENDER TRIM - RH <i>He ne</i>	\$		
SUB TOTAL SPARE PARTS CHARGES		\$	6,050.00	