

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Made: Asher

Not Authorized
also
n/s 4200
Hdays

VEHICLE No: SJM 3062P

1PC	FRONT BUMPER	566.10	Dis	\$688.10	/
1PC	FRONT BUMPER REINFORCEMENT		R	\$399.20	X
1PC	FRONT BUMPER FOG LAMP COVER N/S	105.10	m/s	\$165.30	/
1PC	FRONT BUMPER FOG LAMP N/S	388.20	Cra	\$450.80	/
1PC	FRONT BUMPER TOP RUBBER		nu	\$88.20	/
1PC	FRONT BUMPER SIDE RETAINER N/S		cu	\$66.50	/
1SET	FRONT BUMPER CLIPS		nu	\$50.00	/
1PC	FRONT FENDER N/S	581.10	Buc	\$891.20	/
1PC	FRONT FENDER INNER SHIELD N/S	245.50	Toa	\$299.30	/
1SET	FRONT FENDER INNER SHIELD CLIPS N/S		nu	\$50.00	/
1PC	FRONT FENDER 'VVTI' ELBLEM N/S		nu	\$68.50	/
1PC	HEADLANP N/S	785.30	Scn/cro	\$1,299.20	/
1PC	WIPER WASHER TANK	266.50	de	\$788.50	/
1PC	FRONT SHOCK ABSORBER N/S		Su	\$429.50	X
1PC	FRONT LOWER ARM N/S	466.10	Seaf	\$699.20	/
1PC	FRONT KNUCKLE ARM N/S	525.30	Set	\$650.00	/
1PC	FRONT KNUCKLE ARM BEARING N/S	295.10	nu	\$355.10	/
1PC	FRONT DRIVE SHAFT N/S		11	\$1,488.20	X
				\$8,926.80	

(25m)

S.NETT				
1PC	FRONT TYRE N/S		cu	\$200.00 602 120
1PC	FRONT SPORT RIM N/S		m/suf	\$650.00 400
TO CHECK WIRING				
				\$50.00 20
TO REFILL AIR CON GAS				
				11 \$120.00 X
TO CONDUCT WHEEL ALIGNMENT				
				\$150.00 80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE				
				\$380.00 120
TO SPRAY RUST PROOFING				
				\$100.00 30
LABOUR FOR PANEL BEATING & REPLACED PARTS				
				\$800.00 400
TO PUTTY & SPRAY PAINTING				
				\$880.00 600
TOTAL				\$12,256.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1- 4547.5
252
9- 3410.62
S. 2520.00
L- 1330.00
5260.62