

3A Automobile Pte Ltd

No 120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

Date: 5-Aug-2020

MS First Capital Insurance Ltd

36 Robinson Road

#16-01

Singapore 068877

Email: MotorClaims@msfirstcapital.com.sg

Attn: Claims Officer

Dept: Motor Claim Department

Vehicles Number: SMP 760 B

Make and Model: Honda Shuttle Hybrid

Date Of Accident: 1-Aug-2020

Tel: 65073848

Fax: 65073849

Unit	List Items	Units Price	Prices
1	pc Driver Side Door	\$ 757.20	\$ <i>btv</i> 757.20
1	pc Rear Door RHS	\$ 799.50	\$ <i>btv</i> 799.50
1	pc Rear Fender RHS	\$ 1,010.90	\$ <i>Ry</i> 1,010.90
1	pc Side Mirror RHS	\$ 527.50	\$ <i>bmv</i> 527.50
<i>supp</i> Rear taillamp RH - cut ✓ Frt RH door moulding cut ✓		S/Total	\$ 3,095.10
		Less 20%	(\$619.02)
			\$ 2,476.08

Labour Charges

To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint On All Affected Areas with Oven Spray Booth Facilities.		700
	\$	1,100.00
To Remove & Replace the Damaged Parts as Listed Above, including Reinstallments of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts.		600
	\$	750.00
Total		\$ 4,326.08

Yours faithfully,

3A Automobile Pte Ltd

Person to contact: Alwin / Lydia

Mobilephone : 9786 8677 / 6738 7777

Taufik 97495749
'WP'

6/8/20 @ 1130

taufik@lkhauto.com

**Resurvey before paint
part by part.*

05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: