PLEASE ARRANGE TO SURVEY VEHICLE AT NO.8 KAKI BUKIT AVE 4 GATE 2 #03-21 SINGAPORE 415875

LINDA LIAO STK AUTO (S) PTE LTD

Date:

30/07/2020

To:

China Taiping Insurance (Singapore) Pte. Ltd.

Attn:

Motor Claim Department

Owner:

GONG XIAOQI

LIBERTY INSURANCE PTE LTD

Certificate Number: SI19V14073/VOC/R00

Vehicle Number:

SMG3506Y

HONDA CITY 1.5V Make & Model:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Accident Date: 29/07/20 20 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMO	UNT	SURVEYOR APP.
QTY 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	TAILGATE TAILGATE LOGO TAILGATE LOGO TAILGATE EMBLEM "CITY" TAILGATE EMBLEM "I-VTEC" TAILGATE LAMP RH TAILGATE LAMP LH TAILGATE LAMP LAMP LAMP LAMP LAMP LAMP LAMP LAMP	164280 s s s s s s s s s s s s	586.60 26.00 16.00 85.00 85.00 125.30 250.70 250.70 580.60 95.00 45.00 26.00 26.00 365.60 185.60 65.00 292.51 2,632.59	SURVEYOR APP. Heory of Admin 12/08/20
10 10	REAR BUMPER REVERSE SENSOR REAR BUMPER CLIPS DUIT Charge TO STRAIGHTEN AND PANEL BEAT ACCIDENT TO SPRAY PAINT ON ACCIDENT AREAS TO CHECK WIRING AND COMPUTER DIAGNO TO RUST PROOFING ACCIDENT AREAS	\$ NT AREAS \$ OSTIC TEST \$	800.00 800.00 2,000.00 150.00 150.00	30 505 700 Adria 9 500 700 P/P 01/08/20 4 049
	Sub Total Grand Total	1430 \$	4,300.00 7,732.59	total: 2774.24 CPIP).