振 明 摩 哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883 Tel: 6747-4810 Fax: 6745-5018 cmmotors@singnet.com.sg **ESTIMATE**

Our Ref: EST186/20/CIS Your Ref: To be advised

6-Aug-20

MS First Capital Insurance Ltd

36 Robinson Road #16-01 City House Singapore 068877

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimate cost of repair to Nissan NV350 no: GBC9107C

Date of accident: 01-08-2020		
Parts supply (Nett):		
1 pc Front bumper		571.9
4 pcs Front bumper socket clip @\$5.00		20.00
1 pc Headlamp	_	441.90
		461.90
	Less 10%:	(46.19)
S/Nett Items		
1 pc Front R/h door sticker - Co reg (S/Nett)		20.00
		435.71
Labour charges:		
To panel beating, welding, removing damaged parts and replacement of the parts		
as mentioned above etc.		200.00
To respray affected part.		500.00
To remove & refit of wirings.	_	30.00
	S\$	1,165.71