



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Supplementary Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2008-098 (SUP)
DATE : 31-Aug-2020
POLICY NO. : P10124736R01
VEHICLE REG. NO. : SKZ6102H
VEHICLE MAKE : BMW 116D-1.5 D 5DR HATCH

TO Motor Claim Department
AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED
190 Clemenceau Avenue #03-01,
Singapore Shopping Centre, Singapore 239924
Tel: 6221 2199 Fax: 67250853

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Acoustic (Engine) Cover (Insulator) / BR	1	\$ 115.01	\$ 115.01
2	Preheating Control Unit / BR	1	\$ 177.81	\$ 177.81
3	Vacuum (Electric) Valve Solenoid (8570591) / PR	2	\$ 73.00	\$ 146.00
4	Vacuum Hose (BLACK) / IVRC	2	\$ 30.69	\$ 61.38
5	Vacuum Hose (RED) / NEC	1	\$ 31.84	\$ 31.84
6	Gasket Ring (D:11mm) for Compressor-Condenser / Acc 7 / NEC	1	\$ 10.46	\$ 10.46
7	Gasket Ring (D:17mm) for Compressor-Condenser	1	\$ 10.92	\$ 10.92
8	Gasket Set for Oil Filter Housing / NEC	1	\$ 51.26	\$ 51.26
9	Diesel Dip Stick / BR	1	\$ 36.36	\$ 36.36
10	Cylinder Head Pipe / cadmy pipe / BR	1	\$ 110.76	\$ 110.76
11	EGR Temperture Sensor / BR	1	\$ 103.88	\$ 103.88
12	Boosting Pressure Sensor / BR	1	\$ 110.38	\$ 110.38
13	Part Cost Plus 10%			\$ 96.61
Total Spare Parts				\$ 1,062.67
SPECIAL NETT				
14	BMW Engine Oil / Nec	1	\$ 90.00	\$ 90.00
15	BMW Coolant / Nec	1	\$ 30.00	\$ 30.00
Total Special Nett				\$ 120.00
LABOUR				
16	Remove, Refit A/C Condenser, Radiator & Refill A/C Gas / Nec	1	\$ 100.00	\$ 100.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 100.00
Amount Before Excess	\$ 1,282.67
Add GST @ 7%	89.79
Total Amount Payable	\$ 1,372.45

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: