



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI20008227/Asf3e2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-11-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 3279J	Veh. Inspected	SJC 493B
Policy No.		Coverage (\$)	0.00
Claim No.	DM20HO01125-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	11/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305048201	Colour	SILVER
Odometer	238804	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	HABILEAD	6 mm
L/H Front Tyre	195/55 R15	HABILEAD	6 mm
R/H Rear Tyre	195/55 R15	HABILEAD	6 mm
L/H Rear Tyre	195/55 R15	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/08/2020	Inspection Date	11/08/2020
Survey held at	WIN AUTO ENTERPRISE BLK 1033 EUNOS AVE 5A #01-31 SINGAPORE 409703		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
--	------------------------