

First cap

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

08/08/2020

Owner: MOHAMAD AZELI BIN AHWAN

ESTIMATE TO REPAIR TOYOTA CAMRY 2.5A - SMK8366E

Not Authorized

1/1 Lmy &
Purong Afa Palm
8 days

1pc	front LH fender	\$ 781.50	X
1pc	front LH fender "HYBRID"	\$ 85.25	✓
1pc	front LH side windscreen pillar	\$ 681.50	X
1set	front windscreen moulding	\$ 195.58	X
1pc	front LH side mirror	\$ 681.52	✓
1pc	front LH side mirror cover	\$ 181.50	✓
1pc	front LH door	\$ 1,781.50	✓
1pc	front LH door handle (chrome)	\$ 381.50	✓
1pc	front LH door handle base	\$ 358.20	✓
1pc	front LH door moulding (chrome)	\$ 381.25	✓
1pc	front LH door frame top moulding (chrome)	\$ 358.25	✓
12pcs	front LH door frame top moulding rivet @\$8.00	\$ 96.00	✓
1pc	front LH door garnish	\$ 195.50	✓
1pc	front LH door glass	\$ 981.25	✓
1pc	front LH door panel (tirm)	\$ 1,850.25	✓
1pc	front LH door inner rudder	\$ 281.50	✓
2pcs	front LH door inner frame sticker @\$171.25	\$ 342.50	✓
1pc	rear LH door	\$ 1,681.50	✓
1pc	rear LH door moulding (chrome)	\$ 381.25	✓
12pcs	rear LH door frame top moulding rivet @\$8.00	\$ 96.00	✓
1pc	rear LH door inner frame sticker @\$171.25	\$ 342.50	✓
1pc	rear LH door handle (chrome)	\$ 381.50	✓
1pc	rear LH door handle base	\$ 358.25	✓
1pc	rear LH fender	\$ 1,285.50	✓
1set	rear windscreen moulding	\$ 191.50	✓

\$ 14,332.55

less 25%

\$ 3,583.14

\$ 10,749.41

1set	door visor	Prt
1pc	front LH door glass soler film	
	windscreen sealant	

CM	s.nett	\$ 380.00	✓
me	s.nett	\$ 160.00	100JA
me	s.nett	\$ 180.00	40JA

Balance c/f

\$ 11,469.41



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

08/08/2020

Owner: MOHAMAD AZELI BIN AHWAN

ESTIMATE TO REPAIR TOYOTA CAMRY 2.5A - SMK8366E

Balance b/f \$ 15,052.55

remove & refit front & rear windscreen glass	\$ 240.00	120
remove & refit LH front & rear door glass	\$ 160.00	120
tuffkote	\$ 280.00	90
wiring	\$ 250.00	40
spray painting	\$ 1,800.00	1150
labour charges	\$ 1,800.00	1000
Total	<u>\$ 19,582.55</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

