

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.08.2020

Time: 16:34:05

Page: 1

CHINA

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305415560
 REGN NO : SH 9106C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 14.04.2016
 DATE/TIME IN : 07.08.2020 12:55
 ACCIDENT DATE : 07.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	X	} unit
0002	04-01-0101-011-A	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	X	
0003	04-01-0103-0640-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	X	
0004	04-01-0103-0592-G	I40VC PANEL ASSY-FR DR RH	1	2,256.40	20.00	1,805.12	bt✓	
0005	04-01-0103-0594-G	I40VC MIRROR ASSY-RR VIEW	1	670.00	20.00	536.00	bro✓	
0006	04-01-0103-0573-G	I40VC PANEL-FENDER RH#	1	663.00	20.00	530.40	bt✓	
0007	04-01-0103-0810-G	I40VC MOULDING ASSY-SIDE	1	341.40	20.00	273.12	de✓	
0008	04-01-0103-0595-G	I40VC PANEL ASSY-RR DR RH	1	2,201.10	20.00	1,760.88	Rx	
0009	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	112.50	20.00	90.00	de✓	
0010	28-01-0103-0003-A	(I40)FRT DOOR LOGO SONATA	1	75.00	2.00-	75.00	de✓	
0011	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00	0.20	80.00	de✓	

SUB-TOTAL : 6,029.56

3389.64

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 07.08.2020
Time: 16:34:05
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305415560
REGN NO : SH 9106C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.04.2016
DATE/TIME IN : 07.08.2020 12:5
ACCIDENT DATE : 07.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 L	PANEL BEATING	840.00	560	
0001 23-502	SPRAYPAINT ON AFFECTED AREA	1050.00	800.	
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30.	
0003 20-02	TRANSFER OF DOOR FRT RH	120.00	60	
0004 20-02	REMOVE/REFIX DOOR PARTS TO ASSIST REP Rear RH	120.00	X RM	
0005 20-08	ADJUST FRONT WHEEL ALIGNMENT	80.00	✓	
			1530.	
		SUB-TOTAL : 2,260.00		

TOTAL : 8,289.56

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanpin 97495749
WP
Insurance Resurvey after repair
tanpin@ltharta.com
03/04 days
7/8/20 @ 5pm

3389.64
1530
4919.64
1/8/3950 \$
3 days

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: