

TO : MOTOR CLAIM DEPT.
ATTN : TP VEH NO : PC7725R

ESTIMATE REPORT 1st QUOTATION

OWNERS PARTICULAR
NAME : NATIONAL CAR RENTALS PTE LTD
ADDRESS :

LICENSE NO : SKW3658G
MAKE / MODEL : MAZDA 3
OWNER'S INSURER : NTUC
JOB-CODE : TP

CONTACT :

CHASSIS NO : JM6BN24A8H0156947
ENGINE NO :

ACCIDENT DATE : 7-Aug-20

CLAIM DETAIL

MATERIALS

- 1 FRONT HEADLAMP LH
- 2 FRONT HEADLAMP LOWER BRACKET LH
- 3 FRONT BUMPER
- 4 FRONT BUMPER SIDE RETAINER LH
- 5 FRONT BUMPER SIDE RETAINER RH
- 6 FRONT BUMPER BRACKET LH
- 7 FRONT BUMPER FOGLAMP COVER LH
- 8 FRONT BUMPER FOG LAMP
- 9 FRONT BUMPER LOWER GRILLE
- 10 FRONT BUMPER LOWER GRILLE CHROME MOULDING
- 11 FRONT BUMPER REINFORCEMENT
- 12 FRONT BUMPER LOWER GARNISH
- 13 FRONT GRILLE LOGO
- 14 FRONT GRILLE
- 15 FRONT GRILLE CHROME LH
- 16 FRONT GRILLE CHROME RH
- 17 FRONT FENDER LH
- 18 FRONT FENDER INNER SHIELD LH
- 19 FRONT ABSORBER LH
- 20 FRONT ABSORBER TOP MOUNTING LH
- 21 FRONT WHEEL HUB W/BEARING
- 21 FRONT LOWER ARM LH
- 22 FRONT CONTROL ARM LH
- 23 FRONT KNUCKLE ARM LH
- 24 FRONT CAPITAL
- 25 WING MIRROR ASSY

QTY	QTYO-PRICE	DISC. %	DISC. PRICE	SUR. DISP	REV. PRICE
Qty 1.00	2295.00	10.00	2065.50	Y	✓
1.00	28.00	10.00	25.20	Y	X
Buck 1.00	1025.00	10.00	922.50	Y	✓
Dis 1.00	56.00	10.00	50.40	Y	✓
1.00	56.00	10.00	50.40	Y	X
R 1.00	43.00	10.00	38.70	Y	X
Qty 1.00	149.30	10.00	134.37	Y	✓
1.00	318.50	10.00	286.65	Y	✓
1.00	452.00	10.00	406.80	Y	X
1.00	106.48	10.00	95.83	Y	X
R 1.00	410.00	10.00	369.00	Y	X
1.00	36.00	10.00	32.40	Y	X
1.00	31.20	10.00	28.08	Y	✓
1.00	522.00	10.00	469.80	Y	X
1.00	142.20	10.00	127.98	Y	X
1.00	142.20	10.00	127.98	Y	X
Qty 1.00	325.00	10.00	292.50	Y	✓
Dis 1.00	158.00	10.00	142.20	Y	✓
1.00	289.70	10.00	260.73	Y	X
1.00	106.70	10.00	96.03	Y	X
1.00	146.80	10.00	132.12	Y	✓
Dis 1.00	333.90	10.00	300.51	Y	✓
Dis 1.00	333.90	10.00	300.51	Y	✓
Qty 1.00	398.00	10.00	358.20	Y	✓
1.00	3928.00	10.00	3535.20	Y	X
Qty 1.00	786.00	10.00	707.40	Y	✓

TOTAL (PARTS) : 11356.99

SPECIAL NET ITEM

- 1 FRONT FENDER INNER SHIELD CLIPS
- 2 FRONT BUMPER CLIPS

Not Authorised
6/1 Aug 85 Book
Permy After Part
5 day

208

726

- 3 FRONT BUMPER LOWER SPOILER
4 FRONT SPORT RIM LH
5 FRONT TYRE LH

Per
Adi
Per

0.00 680.00 Y X
0.00 680.00 Y ✓
0.00 380.00 Y X

TOTAL (PARTS):

1840.00

LABOUR

- 1 STRAIGHTEN & PANEL BEAT ACCIDENT AREAS
2 SPRAY PAINTING ON ACCIDENT AREAS
3 CHECK AND REPAIR WIRING SYSTEM
4 RESPRAY TUFF KOTE ON ACCIDENT AREAS
5 R&R FRONT SUSPENSION COMPONENT LH
6 COMPUTERISED WHEEL ALIGNMENT AND BALANCING TYRE

5001
6801
201
301
7801
601

1.00 1200.00 Y
1.00 1400.00 Y
1.00 120.00 Y
1.00 120.00 Y
1.00 280.00 Y
1.00 120.00 Y

TOTAL (LABOUR):

3240.00

TOTAL PARTS & LABOUR

17695.88

EXCESS : S\$

NO. OF DAY : 05

RE-SURVEY : ~~BEFORE~~ / AFTER PAINTING

~~PARTS~~ OR LUMP-SUM

: S\$

DATE OF SURVEY : 12 / 8 / 20

SURVEY BY : Kenneth

CONTACT NO: _____

FAX NO: _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~respray~~ grey painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____