MYCAB PTE LTD REPAIR ESTIMATE

Vehicle No.:

SHA1881S

Make Model

DOA

TOYOTA **PRIUS**

Date

Insurance:

MVA

: CHIANG /NTUC

Qty /		Parts Description / Labour	Qty	Unit Price	Amount
j					
1	1	REAR BUMPER			\$458 60 de
1	1.	REAR BUMPER UNDER COVER			\$552.60 de
j	1	REAR BUMPER UNDER SIDE RH			\$232.00 d
(T)	1	REAR BUMPER REINFORCEMENT			\$318.80
	10	BUMPER CLIPS			\$22.00 neg
	1	REAR BUMPER SIDE RETAINER RH			\$112.70
	1	TOWING COVER			\$82.70 M
		SUB TOTAL		1347.40	\$1,779.40
		LESS 25%		1010.92.	\$444.85
					\$1,334.55
	1	REVERSE SENSOR		10.00%	135.70 X
	1	REAR BUMPER MAT			135.70 X 50.00 W
	'	Marentisement Fender	09.00128	(00 \$172.13 NG
				150.	
		<u>Labour Charge</u>			
		PANEL BEATING			600.00 32
		SPRAY PAINTING			400.00
		WIRING		580	ر 60.00
		TUFF KOTE			60.00 X
		REMOVE/REFIX REVERSE SENSOR			60.00 35
		TOTAL LABOUR		1740.92	\$1,180.00
		ESTIMATE TOTAL		c/5\$1400	\$2,686.68
				2 days	¥2,000.00
				- Coop 4	7

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taylor 97415749

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting • To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: