

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1943Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	DEFORMED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR LICENCE PLATE LAMP LH	NOT NECESSARY	60.40	-
1	REAR LICENCE PLATE LAMP RH	NOT NECESSARY	60.40	-
1	REAR BUMPER LOWER CTR MOULDING	TO REPAIR SEE LABOUR	155.00	-
1	BOOTLID EMBLEM 'IONIQ'	NECESSARY	31.30	31.30
1	BOOTLID EMBLEM 'HYBRID'	NECESSARY	24.30	24.30
	LESS 20% DISCOUNT		-252.81	-197.65
			1,011.24	790.60
	NETT ITEMS			
1	BOOTLID COMFORTDELGRO LOGO (N)	NECESSARY	20.00	20.00
1	BOOTLID TEL. NO STICKER (N)	NECESSARY	10.00	10.00
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
1	REAR NUMBER PLATE (N)	CRACKED	25.00	25.00
	LESS 10% DISCOUNT		-	-23.50
			235.00	211.50
	SPECIAL NETT ITEMS			
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER CTR MOULDING.		500.00	480.00
	SPRAY PAINTING CHARGE.		450.00	400.00
	WIRING CHARGE.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			1,120.00	940.00
	GRAND TOTAL		2,416.24	1,992.10

Report Ref No. NS/INC20008318/T1sf3s2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC20008318/T1sf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

The

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.