

WORLD AUTO PTE LTD

NO.5, KIM CHUAN LANE

S'pore 537070

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AIG ASIA PACIFIC INSURANCE

78 SHENTON WAY #07-16

079120

Attention : Motor Claim Department

Contact : 64193000

WORLD AUTO CONSULTANTS hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate : ES190150

Date : 07/08/2020

Vehicle Num. : SMR 7415S

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 07/08/2020

Claim No. : TP/2665/2020

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	FRONT BUMPER <i>cut</i>		780.00
3.	1	FRONT BUMPER SIDE RETAINER L/H X NN		45.00
4.	1	FRONT GRILLE BASE <i>cut</i>		420.00
5.	1	HEADLAMP ASSY LH X NN		1,450.00
6.	1	HEADLAMP LOWER BRACKET LH X NN		78.00
7.	1	FOG LAMP GARNISH LH X NN		80.00

List TotalS\$:

1200

2,853.00

20.00% Discount S\$:

570.60

960

2,282.40

1.	1SET	SPECIAL NETT ITEMS :		
2.	1	FRONT BUMPER CLIP <i>MC</i>		30.00
		FRONT NUMBER PLATE WITH CASING <i>scr</i>		50.00

Special Nett Total S\$:

80.00

LABOUR :

REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE
REPAIRS INCLUDING PANEL BEAT AND STRAIGHTEN FRONT
SUPPORT PANEL WHERE NECESSARY, AND REPLACE ABOVE PARTS

200 . 400.00

PUTTY AND SPRAY PAINT ALL AFFECTED AREAS

200 . 400.00

Labour Total S\$:

800.00

1430

-20%: 1150

E. & O.E.

Total S\$:

3,162.40

for WORLD AUTO PTE LTD

20 days .
part by part . 17/8/2020 .
before part photos .

Guo Qiang - 82880282

Guo Qiang @ lkk auto . com