

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 06 Oct 2020

Preliminary Advice

Insured Vehicle No	: GBH5668A		
TP Vehicle No	: SLE710R	Accident Date	: 12/08/2020
Make	: INFINITI Q50	Assignment Date	: 13/08/2020
Date of Inspection	: 05/10/2020	Est. Duration of Repair	: 4
Inspection At	: WEARNES AUTOMOTIVE PTE LTD (HQ) 45 LENG KEE ROAD SINGAPORE 159103		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,286.40
Revised Amount	:S\$	8,930.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,930.70

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :