



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20003522/Qvf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 17-08-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3565B	Veh. Inspected	FBG 5689U
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19120276	Excess (\$)	0.00
Assign From	MEKAVATHANAN	Assign Date	20/07/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA FZ16ST	c.c	153
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	ME145S094C2005713	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	100/80-17	MICHELIN	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	100/80-17	MICHELIN	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, N/S AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2019	Inspection Date	03/03/2020
Survey held at	TUNE IN MOTOR BLK 1016 YISHUN PARK A #01-214 SINGAPORE 768758		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------